

Planning Department 345 High Street, 3rd floor Hamilton, Ohio 45011

> Architectural Design Review Board May 16, 2023 @ 4:00 p.m. Council Chambers First Floor, 345 High Street Hamilton, Ohio 45011

NOTE: Agenda and Reports may be amended as necessary or as required. Applicants, Please Review Your Proposal for accuracy.

Board Members

| Bloch | Combs | Essman | Jacobs | Moeller |
|-------------|----------|-----------|-----------|-------------|
| (Torgersen) | (Powell) | (O'Neill) | (Wieland) | (Vaughn) |
| | | | | |
| Vacant | Sandlin | Schneider | Spurlock | Weltzer |
| | (White) | (Vacant) | (Mills) | (Ripperger) |
| | | | | |

- I. Roll Call:
- II. <u>Swearing in of Those Providing Testimony to the Board:</u>
 - 1. Notary Public Liz Hayden

III. Conflict of Interest

Prior to consideration of the following agenda items, each member should examine the agenda to determine whether he or she has any conflict of interest with any agenda item. If so, please note the agenda item for which you intend to abstain or recuse yourself as an exception to the upcoming motion. You may not discuss or vote on any item you have a conflict of interest with or act in any way to influence the deliberation or vote.

Motion: I move that a note be made upon the minutes that each member of the ADRB was furnished a copy of the agenda prior to its being considered at this meeting, and that, with the exception of the items so noted, no member has identified any conflict of interest regarding any agenda item.

- IV. <u>Old Business Properties Seeking COAs</u>
 - 1. <u>10 Kirk Ave (Ohio Historic Inventory) Window and Door Replacement,</u> <u>Work Without a COA</u>

Motions:

- ADRB move to <u>approve</u> the COA request to replace the existing Jeld Wen windows with ______windows, reinstall all removed/covered transom windows, install new front door, and approve Mastercraft steel doors as installed (side and rear) after determining it maintains compliance with Section 2600 of the Hamilton Zoning Ordinance and ADRB Policies & Guidelines.
- ADRB move to <u>deny</u> the COA request as proposed, as it is not compliant with Section 2600 of the Hamilton Zoning Ordinance and/or ADRB Policies & Guidelines.
- 2. <u>770 & 808 Maple Ave (Ohio Historic Inventory) Gutter Installation and</u> <u>Transom Windows</u>

Motions:

- ADRB move to <u>approve</u> the COA request for gutter installation (770 & 808 Maple) and transom repair (770 Maple) as proposed after determining it maintains compliance with Section 2600 of the Hamilton Zoning Ordinance and ADRB Policies & Guidelines.
- ADRB move to <u>deny</u> the COA request as proposed, as it is not compliant with Section 2600 of the Hamilton Zoning Ordinance and/or ADRB Policies & Guidelines.

V. <u>New Business – Properties Seeking COAs</u>

1. 417 N 2nd St (German Village) - Window Replacement

Motions:

- ADRB move to <u>approve</u> the COA request to replace the side and rear basement windows with glass block and the front façade basement windows with custom built wood frame windows as proposed after determining it maintains compliance with Section 2600 of the Hamilton Zoning Ordinance and ADRB Policies & Guidelines.
- ADRB move to <u>deny</u> the COA request as proposed, as it is not compliant with Section 2600 of the Hamilton Zoning Ordinance and/or ADRB Policies & Guidelines.

VI. <u>Administrative Approvals</u>

- <u>1045 Dayton St-</u>Like-for-Like repair and replacement of front porch columns with identical columns. Repaint front porch with matching colors. Repair and replace box gutters on front porch with similar material and style. Repair and replace wooden soffits as needed with similar wood material.
- <u>802 Campbell Ave-</u> Replacement of rear porch light.
- <u>228 N 7th St-</u>Like-for-Like replacement/repair of shingle roof, rubber roof, and recoat front porch roof (similar color for all). Replace/repair wood soffit with like material. Reline box gutter with rubber.
 Replace/repair cedar siding at front entrance with like material and repaint to match existing structure.
- <u>109 N 7th St-</u>Paint body Rookwood Red (SW2802), paint trim Classical White (SW2829), and paint accents Sage (SW2860).

I. <u>Miscellaneous</u>

VII. <u>Approval of Meeting Minutes:</u>1. May 2, 2023

VIII. Adjourn



| То: | Architectural Design Review Board |
|----------|---|
| From: | Dani Baxter |
| Subject: | Old Business - AGENDA ITEM #1 |
| | 10 Kirk Ave – Window and Door Replacement, Work Without a COA |
| | Shawn Hemans, Applicant |
| | Meeting Date: May 16, 2023 |
| | Received Application: January 17, 2023 |
| Impacts: | Ohio Historic Inventory |

May 16, 2023- Updated Information Since Motion to Table:

On April 28, 2023 Ms. Jacobs provided an update regarding her time with the applicant. Ms. Jacobs indicated that she found a door for the applicant to install at 10 Kirk Ave and the transom will be uncovered. Ms. Jacobs also found some woodwork for the interior of the windows, which is necessary to restore the windows to the original size. Ms. Jacobs thinks she can find sashes for the upstairs windows. The window replacement work is still ongoing.

On April 29, 2023 Mr. Hemans provided an update on the progress of 10 Kirk Ave. The applicant reiterated that he purchased a door with Ms. Jacobs assistance and also contacted the window contractors provided by the Planning Department. However, most contractors only perform repairs and restorations; they do not build new windows.

On May 2, 2023 Rick the Window Guy stated that the cost to reproduce the two firstfloor windows measuring 33.5" x 102" in height would be \$2,500 each, the windows would be a wood frame custom made to look historically accurate. This estimate does not include labor or trim work.

On May 6, 2023 Mr. Hemans indicated that he would like the Board to allow him to use either Rick the Window Guy or Champion Windows to replace the first floor windows measuring 102" in height. In addition, he would replace the front façade second floor, all side, and all rear windows with a less expensive option. The applicant stated that the windows on the front façade would have a similar look, even if they were made of different materials. Mr. Hemans indicated that all the currently installed windows would be removed and replacement windows will be installed to fit the original size openings.

On May 7, 2023 Victoria Torgersen provided me with the estimate her husband, Emil Torgersen, provided regarding replacing all five front façade windows with a like for like replacement. The estimate includes five fixed wood windows on the first and second floor on the front façade and is \$6,462. This estimate does not include installation, trim, or paint.

May 16, 2023- Attachments:





EMIL TORGERSEN FINE WOODWOORKING PROPOSAL

| Proposal To: | Proposal Date: | May 7th, 2023 |
|--------------|------------------------------|---------------|
| Shawn Hemans | Due Date of work completion: | EST 6 months |
| anawn Hemans | | |

| NO | DESCRIPTION | QTY | PRICE | SUBTOTAL |
|----|--|-----|------------|----------|
| | Estimate front five wooden windows -fixed: | | | |
| 1 | Cherry Wood BDF 26 | 5 | \$286 | \$1430 |
| 2 | Glass, four panels per window | 5 | \$400 | \$2000 |
| 3 | Window Glazing Putty | 5 | \$11.48 | \$57.40 |
| 4 | Labor Estimate 17 hours per window. (Installation , interior wood trim and paint not included) Half Down Payment Prior to Work | 5 | \$35 | \$2975 |
| | | G | RAND TOTAL | \$6,462 |

Please Note: Windows be in same likeness as original. However, they will be fixed and non operational.

These quotes are all estimations and are subject to change if necessary for material cost.

Emil Torgersen

April 18, 2023- Updated Information Since Motion to Table:

On March 23, 2023 Rick the Window Guy provided an estimate to remake the original wood, two over two style front façade windows (like for like).


- "To remake all 5 windows from scratch and to look and operate like the original wood windows would be \$11,000.
 It would be an additional \$4,000 to install them properly in each opening.
 Interior wood trim adds \$2,500 to look like the original wood trim. It may be there still. I don't know."
- Applicant was notified of this quote and states, "Thanks for the quote but that is too expensive for less than half of the windows needed."

Applicant stated that he has been to multiple antique stores to look for wood doors to install on the property (Wooden Nickel Antique, Building Value, Antique Village, and Restore Fairfield). Mr. Hemans stated he purchased a door and is modifying it to match what the Board requested. Applicant was concerned about buying a door from the antique store and the Board not approving the door and the antique shops not allowing him to return the door if the Board did not approve.

Applicant also stated that he has another option for the front façade windows. This option would be comprised of installing two Jeld Wen, fixed vinyl windows, stacked on top of each other within the existing opening. There appears to be a single vertical muntin in the window. The applicant also noted that there are other windows within this room that can be used for ventilation.

Applicant is requesting that the new window installation be allowed to be completed in phases. Mr. Hemans will complete the front of the home in phase one.

April 18, 2023- Attachments:



New window proposal- Jeld Wen





Original Report:

Introduction

The Applicant, Shawn Hemans, has submitted a Certificate of Appropriateness Application for window and door replacement proposed at 10 Kirk Ave. The proposal involves prior work completed without a COA issued by the Architectural Design Review Board. The applicant replaced the entirety of windows surrounding the home and the three exterior doors without prior approval. The front door transom window was removed and the rear door transom appears to have been decreased in size.

This property is located along High St and is Zoned R-2 (Single-Family Residence). This property is located on the State of Ohio Historical Inventory as the John Kirk residence (BUT075909).

Proposal

- Previous Windows
 - Material- wood (5 front windows, 3 on east side, 6 on west side), vinyl (1 on east side, 1 on rear), glass, and plexiglass
 - o Color-white
 - o Design- overhang, door-style, 2 over 2
 - o Dimensions
 - Front of house- 33.5" x 102" (2); 32.5" x 72" (3)
 - Left side of house- 32.5 x 54" (2); 32.5" x 81" (1); 32.5" x 72" (2)
 - Right side of house- 32.5" x 81" (3); 32.5" x 72" (3)
 - Back of house- 32.5" x 72" (1)
 - Transom windows installed over three first floor doors
- Currently Installed Windows
 - o Material- vinyl, glass
 - o Color- white

- o Design- Jeld Wen Good Series, double hung, model JW1792-00215
- o Dimensions
 - Front of house- 32.5" x 54" (5)
 - Left side of house- 32.5" x 54" (5)
 - Right side of house- 32.5" x 54" (6)
 - Back of house- 32.5" x 54" (1)
- Previous Doors
 - o Material- wood, metal
 - o Color- white
 - o Design-
 - Front of house- wood with ½ glass and scalloped edge around glass, transom above door
 - Right side of house- 6 panel, wood, transom above door
 - Back of house- 6 panel, metal, transom above door
 - o Dimensions
 - Front of house- 36" x 80"
 - Right side of house- 36" x 80"
 - Back of house- 36" x 80"
- Currently Installed Doors
 - o Material- Steel, wood frame
 - o Color- primed white
 - o Design- Mastercraft, 6 panel, Exterior Door, model 4140336
 - o Dimensions
 - Front of house- 36" x 80", transom removed

- Right side of house- 36" x 80", transom remaining
- Back of house- 36" x 80", transom decreased in size

Applicant Provided Window Estimate Information

- 1. Butler County Lumber Quote- (Listed as an approved replacement window based on ADRB Policies & Guidelines)
 - a. Material- vinyl, fibrex composite, glass
 - b. Color-white
 - c. Design- Anderson 100 Series Windows, single hung
 - d. Dimensions- (reference to "grille bar" is similar to muntins and is located between the two panes of glass)
 - i. Unit Size- 32.5" x 102" = \$1,215.66/window
 - 1. Includes ³/₄" Grille Bar (white) running vertically.
 - 2. Two over two window style matching original
 - Comprised of two windows placed on top of each other. Each window is four feet and two and 3/4 inches (4' 2 ³/₄ ") tall. The mullion in the middle connecting the two windows is six inches (6").
 - ii. Unit Size- 32.5 x 72" = \$508.09/window
 - 1. Includes ³/₄" Grille Bar (white) running horizontal and vertically
 - 2. Two over two window style matching original
 - iii. Unit Size- 32.5" x 72" = 469.85/window
 - 1. One over one window style
 - iv. Unit Size- 32.5" x 81" = \$521.21/window
 - Smaller window pane on bottom with mullion located at 1/3 of window height
 - 2. One over one window style

- v. Unit Size- 32.5" x 89.5" = \$611.48/window
 - 1. Includes 3/4" Grille Bar (white) running vertically
 - Smaller window pane on bottom with mullion located at 1/3 of window height
 - 3. Two over two window style
- vi. Unit Size- 32.5" x 102" = \$888.15/window
 - 1. Includes 3/4" Grille Bar (white) running vertically
 - 2. Two over two window style with a transom window
 - 3. Comprised of one window with an additional transom over top. The window is six feet five and a half inches (6' $5 \frac{1}{2}$ ") tall with a two foot (2') transom window over top.
- vii. Total quote to replace all windows = \$9,435.40 \$11,683.73
- 2. Champion- (Not listed as an approved replacement window based on ADRB Policies & Guidelines)
 - a. Material- vinyl, glass
 - b. Color-white
 - c. Design- unknown
 - d. Dimensions
 - i. Unit Size- 34" x 102" = \$3,986/window
 - Total quote to replace the first floor front façade windows = \$7,972
- 3. Infinity from Marvin- (Listed as an approved replacement window based on ADRB Policies & Guidelines)
 - a. Unable to provide windows as their maximum height is 96", due to operating hardware (lift and balance mechanism).
- 4. Scofield Window- (Not listed as an approved replacement window based on ADRB Policies & Guidelines)
 - a. Material-vinyl, glass

- b. Color-white
- c. Design- UltraWeld, UltraWeld 8420 double hung, UltraWeld 8400 picture window
- d. Dimensions
 - i. Unit Size- 32.5" x 102" = \$845.54/window
 - 1. Includes internal muntins running horizontal
 - 2. Two over two window style matching original with a transom window
 - 3. Comprised of one window with an additional transom over top. The window is seven feet (7') tall with an eighteen inch (18") transom window over top.
 - ii. Unit Size- 32.5" x 72" = \$452.22/window
 - 1. Includes internal muntins running horizontal
 - 2. Two over two window style matching original
 - iii. Unit Size- 32.5" x 81" = \$461.13/window
 - 1. One over one window style
 - iv. Unit Size- 32.5" x 72" = \$424.32/window
 - 1. One over one window style
 - v. Total quote to replace all windows = \$7,921.67
- 5. Rick the Window Guy- (Not listed as an approved replacement window based on ADRB Policies & Guidelines)
 - a. Materials- wood, glass
 - b. Color- white
 - c. Design- rebuild sash and window frame as like for like.
 - d. Dimensions- 33.5" x 102" (2 windows); 32.5" x 72" (3 windows)
 - i. Front façade only

ii. Total quote to replace front façade windows- TBD

Hamilton Zoning Ordinance

ADRB Policies & Guidelines

This application broaches the topic of windows in the ADRB Policies and Guidelines. The current Policies and Guidelines do not outline door replacement or installation.

General Window Regulations & Guidelines

A. Critical Parts of Windows that Shall Not Be Altered

The following items will be considered a critical part of the exterior architectural/design elements that shall not be altered on a structure:

- 1. The specific location of each individual window.
- 2. The specific style of each individual window.

3. The number of panes (lights/grids/sashes) of each individual window. (example: 2x2 grid/pane, 4x4 grid/pane, 9x9 grid/pane)

- 4. The specific dimensions of each individual window.
- 5. The specific treatment of the framing for each individual window.

6. The size, width, and placement of window parts, such as but not limited to the sashes, muntins, rail, casing, stile, stool, and apron shall remain unchanged. If these parts are on the exterior of the window, they shall remain on the exterior of the window, (i.e. exterior muntins shall not be moved to the interior of the window pane).

7. The relationship of the above elements and/or related elements for each window in the overall window treatment/design of a structure.

C. Non-Historic Window Replacement

Applications for new windows that will replace existing replacement windows that are not considered historic, including but not limited to existing vinyl replacement windows, can be approved administratively if the applicant proposes a window from the "List of Approved Replacements for Significantly Damaged or Missing Windows" and if they match the historic window in location, style, size, dimensions, grids/sashes/panes, and treatment.

Window Work approval by the Architectural Design Review Board

Replacement of Significantly Damaged or Missing Windows

In the event that the window is significantly damaged or missing, the Architectural Design Review Board may be able to approve a Certificate of Appropriateness for window replacement with a broader list of window types, as long as the proposed window meets the General Window Regulations & Guidelines. This is subject to the following clauses:

- 1. Window is significantly damaged: This means that the window is damaged or rotted 50% or more, or is missing key components.
 - Half of the window is missing
 - Missing window sash and/or frame
 - Damaged/Missing window sill
 - Photo evidence shall be required. A site visit may be requested.
- 2. Window is missing: the window is missing, leaving only a window opening in the façade or a bricked in place where the window once was.
 - Photo evidence shall be required. A site visit may be requested.
- 3. If the window exists but is significantly damaged, the applicant shall provide written or verbal testimony from an experienced window repair contractor or consultant to attest to the window being more than 50% damaged. The ADRB may ask for examples of other projects that the window repair contractor or consultant has completed.
- 4. The ADRB shall make the determination of whether the windows meet the definition of "Significantly Damaged or Missing Windows."

D. List of Approved Replacements for Significantly Damaged or Missing Windows

An applicant can propose a window that is not on this list as long as it meets the General Window Regulations & Guidelines. The Architectural Design Review Board will ask for supporting information, such as but not limited to window design detail, a physical window sample, and documentation from a window contractor or consultant that the window is paintable. The Architectural Design Review Board is not required to approve any windows that are not on the List of Approved Replacements list.

 Jeld Wen, Good Series windows are not on the approved list of replacement windows.

Additional Window Guidance

B. Considerations for Window Replacements:

When the ADRB is reviewing a Certificate of Appropriateness for window replacement, the following information will be considered to determine the appropriateness of replacing historic windows:

- 1. That multiple avenues of preserving the historic windows have been pursued, including consulting a historic window preservation specialist or contractor with demonstrable background and experience in preserving historic windows.
- 2. Difficulty in repairing the existing wood windows or difficulty in obtaining a contractor to repair the existing wood windows.
- 3. Difficulty in obtaining new wood windows or wood composite windows that match the existing wood windows.
- 4. The structure or portion of structure is comparatively more modern or newer than other houses and principal structures in the immediate area. This can include new additions of a structure.
- 5. That the request for window replacement is part of a large scale renovation project in a building that is substantial disrepair and would be in danger of demolition if not for the renovation project.

ADRB requires that the applicants to provide written evidence to support these considerations, including estimates, quotes, and/or recommendations from a professional and/or letters on letterhead with signature of the professional(s) involved in the assessment.

Information about the overall project and building condition is requested. Cost information on structural stabilization work, historic gutter rehabilitation, and other relevant preservation efforts should be included.

C. Other Window Replacement Types

5. Reduction of Window or Filling In Window

The following window proposals are conditional and generally considered inappropriate. Such proposals will be reviewed with the highest scrutiny and will only be approved when appropriate to the structure and historic district.

The ADRB may also assign additional conditions to the approval of these window projects.

The reduction of a window opening or filling in of a window opening shall only be considered in the following cases.

- Window reduction shall only be located on the rear or side facade and is not highly visible from the street or sidewalk.
- The 'fill' of the previous window shall be consistent with the material and form of the façade. (i.e. on a brick façade, the filled portion shall be brick; no plywood, painted wood panel, vinyl, plastic, or metal on any façade type)
- The replacement window is for a special, utilitarian, and/or specific renovation of the structure (the most common being, new bathroom, or closet).

- The structure or portion of structure is comparatively more modern or newer than other houses and principal structures in the immediate area. This can include new additions of a structure.
- Structure is a commercial or industrial building and the proposal is necessary for the viability of the business.

Staff Comments

- 1. Planning Department staff could not verify the damage to the original windows and doors. They were removed from the property before Planning Department staff was aware of renovations.
- 2. Planning Department Director, Liz Hayden, sent a Notice of Violation letter to the property on January 12, 2023 regarding work being completed without a COA.
- 3. Planning & Zoning Specialist, AJ Schweier, went on site January 12, 2023 and hand delivered the Notice of Violation letter to the applicant.
- 4. Applicant installed the Jeld Wen windows in September 2022. Windows and labor cost approximately \$20,000.
- 5. Planning Department staff met with the applicant multiple times to determine the best path forward to ensure due diligence was performed concerning obtaining window replacement estimates.
- 6. Applicant would prefer to replace existing Jeld Wen vinyl windows with the Scofield windows presented in the estimate.
- 7. Given the complexities of the application staff has communicated to the applicant this hearing might take two meetings to complete the vote.

Motion:

The ADRB may approve, modify, or deny the COA request as presented to the Board. Planning Department staff has prepared the following motions for the Board's consideration:

• ADRB move to <u>approve</u> the COA request to replace the existing Jeld Wen windows with Scofield windows as proposed, reinstall all removed/covered transom windows, install new front door, and approve Mastercraft steel doors as installed (side and rear) after determining it maintains compliance with Section 2600 of the Hamilton Zoning Ordinance and ADRB Policies & Guidelines. ADRB move to <u>deny</u> the COA request as proposed, as it is not compliant with Section 2600 of the Hamilton Zoning Ordinance and/or ADRB Policies & Guidelines.

Attachments:

- 1. Exhibit A Location Map
- 2. Exhibit B Certificate of Appropriateness Application
- 3. Exhibit C Site Plan & Photos
- 4. Exhibit D Rendering & Material Specs for Windows
- 5. Exhibit E Notice of Violation letter delivered January 13, 2023
- 6. Exhibit F Ohio Historic Inventory Sheet

Exhibit A – Location Map



Exhibit B - Certificate of Appropriateness Application



Planning Department 345 High Street, 310 floor Hamilton, Onio 45011

-785-7350

Architectural Design Review Board Fax: 513-785-7359

Email: hamiltonhistoric@hamilton-oh.gov

APPLICATION FOR A CERTIFICATE OF APPROPRIATENESS

_xterior changes made to buildings, outbuildings, landscapes, or other exterior features located within one of the City of Hamilton's Historic Areas or properties individually listed by Ordinance shall not be permitted unless and until the Architectural Design Review Board issues a Certificate of Appropriateness for the action. The ADRB will review the plans, monitor the work and administer the Architectural Conservation/Historic District section (Section 2600) of the Hamilton City Zoning Ordinance.

A fee will be charged for any Certificate of Appropriateness application that is required to be heard before the ADRB, unless the proposed change is returning to or restoring to previous or original historic materials that can be referenced in past Architectural Design Review Board or other official City of Hamilton/State of Ohio Historic Inventory records. A proposal that is Like for Like (A repair or improvement in relation to a property in which the repair or improvement utilizes the existing materials/colors and replaces them with matching materials) does not require ADRB review and will be approved by the Secretary.

A nonrefundable fifty-dollar (\$50.00) fee for Residential property or one-hundred-dollar (\$100.00) fee for Commercial property is due when a Certificate of Appropriateness application is submitted.

| | Fee Sched | ule | | | 1 |
|-----|--|--|------------------|--------------|------------------|
| | Proposal: | | Residential | Commercial | - |
| | Exterior Ch | ange | \$50 | \$100 | - |
| | Like for Like | e Work (no board review) | \$0 | \$0 | - |
| | Return to O | riginal Historic Materials | \$0 | \$0 | |
| | Work without | ut COA Fee (First Occurrence | \$100 | \$200 | |
| | Work W/O (Occurrence | COA Fee (Multiple | \$300 | \$600 | |
| Pre | operty Address: K_ | ERK AVENUE | Ham | ELTON) | OH 4501 |
| Ap | plicant Name: SHAW | N HEMANS | | | |
| | plicant Mailing Address: 496 mer/s Name:N | 3-1- | 2068 | CT JIB | ERTY TWP DH |
| Ow | ner Mailing Address: 4966 | WINDY Rodge E | T. JIBE | ery Twi | Poll 4504 |
| Day | time Contact Phone:347 - 4 | 76-0908 Email | HWSPKO | PERTYGR | out mc Dypho isn |
| App | licant Signature: | | D | ate: - | 17-2022 |
| APP | LICANTS ARE HIGHLY ENCOUR | AGED TO APPEAR BEFORE TH | FROARDTOR | UDDODT | |
| | and the second second second second | UNE II | E DOARD TO S | UPPORT THEIR | APPLICATION |
| | Element and C | the state of the second st | | | AFFLICATION. |
| | Please see P | age 4 for the Meeting Dates a | nd Application I | Deadlines. | APPLICATION. |

| _ Architectural Style o | f Structure/House (put N/A if not known): |
|---|--|
| Paint | Sample Provided (often required) |
| Appearance of | Color: |
| | Manufacturer: |
| Location (body, | window trim, specific trim, accent: |
|] Siding Existing Siding | (style, material, color, location): |
| Proposed Sidin | ng (style, material, color, location): |
| Manufacturer: | Proposed Size: |
| copy of Prese | osing vinyl or aluminum siding, per ADRB Guidelines, applicant must be provided a rvation Brief 8, concerning siding. It is HIGHLY recommended that applicant res and document extensive reasons why vinyl or non-historic siding is being |
| Roof | *Roofing may require a building permit from the Building Department* |
| | material, style, color): |
| | f (material, style, color): |
| Windows V Door P Existing Windo | idous are eventuary pour size of panels wood fitxalass/mit is class, window size bor size 36"x50 530" x80" with ws/Door (style, material, size, color, location): for further waterial the |
| Proposed Wind | dows/Door (style, material, size, color, location): |
| Contraction of the second s | Type (if applicable): |
| material as the other non- his | DRB Guidelines, it is recommended that proposed windows are the same size and e original window opening. Covering of windows is highly discouraged. For vinyl or storic windows, it is recommended to document existing windows, including the I reasons why original windows should be replaced. |
| _] Fence Existing Fence | *Chain-link is discouraged unless certain conditions are met defined by ADRB* (type, material, color): |
| Proposed Fend | ce (type, material, color, location, course): |
| Gutters Existing Gutter | *It is advised that all replaced gutters match the look of the existing* r (material, style, location, color); |
| Proposed Gutt | er (material, style, location, color): |
| Manufacturer: | |
| Soffit | |
| Existing Soffit | (style, material, location, color): |
| | it (style, material, location, color): |
| Other | |
| - | |

WINDOWS/DOORS : The property was purchased on 07-18-2022 and windows and doors were Installed in September 2022. Existing windows before installment was wood and vinyl windows / glass and Perspex material deteriorated beyond repair.

The front of the house was wood window / flexi glass / Perspex. Some of the windows was baton down (blocked out) by plyboard because of vandalism. Existing window size - (2) 331/2" x 102 & (3) 32 ½ x 72. Current Window size Vinyl (5) 32 %"W X 54"L

The left side of the house : Some of the windows on this side was baton down (blocked out) by plyboard as well. Vinyl window was there as well which was vandalized beyond repair. Existing window size – (2) 32 %"W X 54"L, (1) 32 %"W X 81°L & (2) 32 %"W X 72"L Current window size Vinyl (5) 32 %"W x 54"L

RIGHT SIDE: There was vandalism and deterioration with wood/ Perspex / flexi glass as well. Existing window size – (3) 32 M^uw x 81^ul & (3) 32 %^uw x 72^uL Current window size vinyl– (6) 32 %^uW X 54^uL

BACK OF THE HOUSE : There was a damaged vinyl window at the back of the house. Existing window size -(1) 32 %" w x 72" l Current window size vinyl-(1) 32 %"W x 54"L

DOOR: A metal 6 panel door was at the back .

RIGHT SIDE: There was a 6- panel wood door at the right side of the house that was vandalized beyond repair.

FRONT DOOR: There was a 4 panel wood door that has deteriorated beyond repair including door frame, termite has eaten it away.

My title office / realtor / Seller had no information regarding this property being historical. I was made aware when the city reached out to me which was on 01-11-2023 via phone call. I was then provided with a letter following the phone call on 01-12-2023 stating that I should immediately stop work because of the property being historical which I complied.

When they contacted me on 01-11-2023, all windows were already installed in September 2022. The windows and labor cost me approximately \$20,000.00. I am open to a discussion on how we can make this work to maintain the property as historical without making excessive adjustment to the windows and doors.

Thanks for all you do

CHECK ALL THAT APPLY & FILL IN THE CORRESPONDING INFORMATION

DESCRIPTION OF WORK TO BE PERFORMED

Please specify the exact location on the structure, the nature of the work, the materials and methods to be used, and the existing historic features to be repaired or replaced not previously mentioned. Landscape, fence, and out buildings, etc., should include a sketch of the property showing the proposed location. In order to make an appropriate, fair and timely decision the ADRB may request additional detailed information. This may include plans, sketches, photographs, and information about the materials to be used, including brochures, catalog information and earlier the timely decision. information, and paint chips. The more information provided, the better:

| · · · · · · · · · · · · · · · · · · · | |
|--|---|
| | |
| Demolition | NAC AN OWNER REPORTED AND ADDRESS AND |
| Certificate of Approp Conservation/Histor | ate of Appropriateness – Demolition: In the event an application for a oriateness includes demolition of any property in the Architectural to District the applicant shall be required to submit evidence to the Review Board indicating that two of the following conditions prevail: |
| area of the Archite | erty proposed for demolition is not inherently consistent with other properties in its ectural Conservation/Historic District. For example, it may have been built at a time iod of significance of the historic district. |
| B. That the prope significance. | rty proposed for demolition contains no features of architectural and/or historical |
| | o reasonable economic use for the property as it exists or as it might be rehabilitated, asible means or prudent alternative to demolition, |
| | ures listed in Section 2603.1(Central Area Building Inventory) shall be maintained: posal will be accepted: |
| restoring or | evidence showing significant financial infeasibility of preserving, rehabilitating, reconstructing the structure. An example might be providing a pro forma that how the costs of rehabilitation could not be recuperated reasonably through the a building. |
| 2. Without a | a detailed plan of demolition and potential reuse of the property. |
| 3. Without a historical fe | a detailed plan of preserving any remaining exterior architectural features and/or atures of the structure and site. |
| proposal that furth | n of the property would contribute to a significant economic development purpose or hers the City of Hamilton's comprehensive plan, Plan Hamilton. That the demolition tegic economic impact to the historic district or neighborhood as a whole beyond the y. |
| Please a | attach supporting information as a separate document as necessary |
| Application | s can be submitted electronically to <u>HamiltonHistoric@hamilton-oh.gov</u> |
| | |

Exhibit C – Site Plan & Photos

Google Street View Image of Property- May 2019









Previous Front Door



Google Street View Image of Property-July 2018



Photo of Rear of house- December 2016



Existing Site Photos



Front Façade



<u>West Façade</u>







<u>Rear Façade</u>



East Façade



| ANDERSEN WINDOWS & DOORS CREATED DATE 1/23/2023 ZA13/2023 TOT SANGER | TRADE ID | Unit Price Ext. Price | \$1,215.66 \$2,431.32 | RO Size = 33 1/4" x 102 3/4" Unit Size = 32 1/2" x 102" Mull: Factory Mulled, Nonreinforced Join - Factory Assembled Stack Mull, 1/2" Fiberglass Non Reinforced Horizontal Mull Material Mull: Factory Mulled, Nonreinforced Join - Factory Assembled Stack Mull, 1/2" Fiberglass Non Reinforced Horizontal Mull Material Noule Exterior Sash/Panel, With Exterior Sash/Panel, Unit, 1:00 Series Single Casement-CW, 1:3/6" Selback, White Exterior Frame, Milled Argon Fill Finelight Grilles-Between-the-Glass 2 Wide, 1 High, Specified Equal Light Pattern, Mille, Wiltle, 3/4" Grille Bar, Stainless Glass / Grille Spacer, Folding, 1 Sash Locks White, Wilte, Full Screen, Fiberglass Insect Screen 1: 100 Series Single Casement-CW, 100CS 32:5 x 50.75 Full Screen Fiberglass White, Mille, Grille Spacer, Folding, 1 Sash Locks White, Wilte, Full Screen, Fiberglass Insect Screen 1: 100 Series Single Casement-CW, 100CS 32:5 x 50.75 Full Screen Fiberglass White C ENERGY STAR Clear Opening/Unit # Width Height Area (Sq. Ft) Comments: | |
|---|---|-----------------------|-----------------------|---|------------|
| | customer Po# | Location | None Assigned | (02" I/2" Fiberglass Non R le Casement-CW, 1 3 "anel, Unit 1: Stationa Glass 2 Wide, 1 High Sash Locks White, Wh Sash Locks White, Wh Area (Sq. Ft) Con | 6.38200 |
| SOLD TO: | MBER 54 DELIVERY NOTES: | | | Unit Size = 32 1/2" × 102" Assembled Stack Mull, 1/2" Assembled Stack Mull, 1/2" Assembled Stack Mull, 1/2" Any Unit, 100 Series Stage and Grilles-Between-the-Gla and Gri | 45.0560 |
| Ő | 349111 | Operation | Left / Stationary | RO Size = 33 1/4" x 102 3/4" Unit Size = 32 1/2" x 102" Mull: Factory Mulled, Nonreinforced Join - Factory Assembled Stack Mull. 1/2" Fiberglass Non Reinfor Mull: Factory Mulled, Nonreinforced Join - Factory Assembled Stack Mull. 1/2" Fiberglass Non Reinfor Nitle Exterior Sash/Panel, w/White Interior Frame, w/White Interior Sash/Panel, Unit 1: Stationary. Un Unit 1: Tempered Unit 2: Standard Argon Fill Finelight Grilles-Between-the-Glass 2 Wide, 1 High, Spet White, w/White, 3/4" Grille Bar, Stainless Glass / Grille Spacer, Folding, 1 Sash Locks White, Mhite, Fi Insect Screen 11 100 Series Single Casement-CW, 100CS 32.5 x 50.75 Full Screen Fiberglass White, Fi C ENERGY STAR Clear Opening/Unit # Width Height Area (Sq. Ft) Commer | A2 20.3970 |
| SOLD BY: BUTLER COUNTY LUMBER CO. BEI MAIN ST. HAMLTON, OH 45013 513.696-6660 | Abbreviated Quote Report - Customer Pricing auote Name HEMANS/SHAWN ORDER NOTES: | Otv | 2 | RO Size = 33 1/4" x 102 3/4" II: Factory Mulled, Nonreinforced Join - Factory J DCS 2' 8 1/2"X4' 2 3/4" / 100CS 2' 8 1/2"X4' 2 3/4 DCS 2' 8 1/2"X4' 2 3/4" / 100CS 2' 8 1/2"X4' 2 3/4 DCS 2' 8 1/2"X4' 2 3/4" (2000 A 2000 Fill Finelig it 1: Tempered Unit 2: Standard Argon Fill Finelig it 1: Tempered Unit 2: Standard Argon Fill Finelig the, w/White, 3/4" Grille Bar, Stainless Glass / G sect Screen 1: 100 Series Single Casement-CW, ENERGY STAR Clear Opening/Unit # | Q |
| | Quote Rep | Item | 100 | RO Size Mull: Facto 100CS 2*8 White Exte Unit 1: Ten White, w/M Insect Scr Insect Scr SHGC | 0.25 |
| ButterCoun | DIEVIATED OL QUOTE NAME HEMANS/SHAWN ORDER NOTES: | 1 | | Unit # U-Factor | 0.28 |

Exhibit D – Rendering & Material Specs for Windows

Butler County Lumber Estimate-

| | Item | - Off | 2 | Operation | 5 | | Location | Unit | Unit Price | Ext. Price |
|----------|---|---|---|---|---|--|---|---|----------------------------------|--|
| | 200 | 3 | | Fixed/Active | Ne | | None Assigned | | \$508.09 | \$1,524.27 |
| | RO | RO Size = 33" x 72 1/2" | 72 1/2" | | Unit Size | Unit Size = 32 1/2" x 72" | 72" | | | |
| 5 | 100SHS w/White the-Glats Anderse | s 2° 8 1/2°X6 Interior Fran as 2 Wide, 1 in 100 Series | , Unit, 10(me, w/Whi High, Spe s, 1 Sashi | 100SHS 2' 8 1/2"X6', Unit. 100 Series Single-Hung, Equal Sash, 1 3/8" Setback, White Exterior Frame, White Exterior Sash/Panel, wMhite Interior Frame, wMhite Interior Sash/Panel, Fixed/Active, Dual Pane Low-E Standard Argon Fill Finelight Grilles-Between- the-Glass 2 Wide, 1 High, Specified Equal Light Pattern, White, White, 3.4" Grille Bar, Stairless Glass / Grille Spacer, Auto Lock: Andersen 100 Series, 1 Sash Locks White, Half Screen, Fiberglass | g, Equal Sas el, Fixed/Act attern, White Half Screen | h. 1 3/8" Sel tive, Dual Pe . w/White, 3 | back, White Exter the Low-E Standa /4" Grille Bar, Stai | ior Frame, White Er rd Argon Fill Finelig ritess Glass / Grille | Merior S M Grilles Spacer, | ash/Panel, s-Between- Auto Look. |
| U-Factor | Insect S SHGC | Screen 1: 10 ENERGY : | 0 Series 5 STAR Cle | Insect Screen 1: 100 Series Single-Hung, 100SHS 32.5 x 72 Half Screen Fiberglass White C ENERGY STAR Clear Opening/Unit # Width Height Area (Sq. Ft) | S 32.5 x 72 F Width | Half Screen F Height | Fiberglass White Area (Sq. Ft) | Comments: | | |
| | N.2R | Q | | A1 | 28.0000 | 32 2890 | 6 50260 | | | |
| | Item | AR I | к | Operation | 9 | | Location | Unit | Unit Price | Ext. Price |
| | 300 | 9 | | Fixed/Active | Ne | | None Assigned | | \$469.85 | \$2,819,10 |
| | RO S | RO Size = 33" x 72 1/2" | 72 1/2" | | Unit Size | Unit Size = 32 1/2" x 72" | 12" | | | |
| 15 | 100SHS w/White Spacer, | 2' 8 1/2"X6' Interior Fran Auto Lock, A | , Unit. 100 Tre, w/Whi Andersen | 100SHS 2' 8 1/2"X6', Unit. 100 Series Single-Hung. Equal Sash. 1 3/8' Setback, White Exterior Frame. White Exterior Sash/Panel. w/White Interior Frame, w/White Interior Sash/Panel, Fixed/Active. Dual Pane Low-E Standard Argon Fill Stainless Glass / Gnile Spacer, Auto Lock, Andersen 100 Series, 1 Sash Locks White, White, Half Screen, Fiberglass | g, Equal Sasi el, Fixed/Act Locks White, | h, 1 3/8" Sel tive. Dual Pa White, Half | back, White Exter ine Low-E Standa Screen, Fiberglas | tior Frame, White Er rd Argon Fill Stainte ss | xterior Si iss Glass | ash/Panel. s / Grille |
| U-Factor | Insect S SHGC | Screen 1: 100 ENERGY 5 | 0 Series S STAR Cle | Insect Screen 1: 100 Series Single-Hung, 100SHS 32.5 x 72 Half Screen Fiberglass White C ENERGY STAR Clear Opening/Unit # Width Height Area (Sq. Ft) | S 32.5 x 72 H Width | Half Screen F Height | Fiberglass White Area (Sq. F1) | Comments: | | |
| | 0.31 | ON | p. | At | 29.0000 | 32,2890 | 6,50260 | | | |

| Ext. Price | \$2,084.84 | | hite Exterior tainless | | | \$8,859.53 \$0.00 \$0,00 \$575.87 \$9,435,40 | | a wraps | |
|------------|---------------|---------------------------|---|--|---------|--|--------------------|--|--|
| rice | 51 | | N (HIII O | | | | | uliding | |
| Unit Price | d \$521.21 | | , White Exterior Fran tw-E Standard Argon ten, Fiberglass | Comments: | | SUB-TOTAL: FREIGHT: LABOR: TAX: TOTAL: | DATE | to allow for use of b | |
| Location | None Assigned | 81" | riel, 1 3/8" Setback tive. Dual Pane Lo e, White, Half Scre | | 5.05540 | | | ed to be increased | |
| | | Unit Size = 32 1/2" x 81" | se Cottage/O mel. Fixed/Ac h Locks Whit | Half Screen Height | 25.1027 | | | s and may ne | |
| - U | tive | Unit Size | tung, Revers rrior Sash/Pa | IS 32,5 × 81 Width | 29,0000 | | | in minimums | |
| Operation | Fixed/Active | | 100SHS 2' 8 1/2"X6' 9", Unit, 100 Series Single-Hung, Reverse Cottage/Oriel, 1 3/8" Setback, White Exterior Frame, White Exterior Sash/Panel, Fixed/Active, Dual Pane Low-E Standard Argon Fill Stanless Glass / Grille Spacer, Auto Lock, Andersen 100 Series, 1 Sash Locks White, Half Screen, Fiberglass | Insect Screen 1: 100 Series Single-Hung, 100SHS 32,5 x 81 Half Screen Fiberglass White C ENERGY STAR Clear Opening/Unit # Wittin Height Area (Sq. Ft) | A1 | | | * All graphics as viewed from the exterior. ** Rough opening dimensions are minimums and may need to be increased to allow for use of building wraps or flashings or still panning or brackets or fasteners or other ltems. Thank you for choosing Andersen Windows & Doors. | |
| Oth | 4 | RO Size = 33" x 81 1/2" | I 1/2"X6" 9", Un w/White Interk Spacer, Auto | en 1: 100 Serie VERGY STAR | ON | | | arion, " Rough - s or fasteners o ndersen W | |
| Item | 400 | RO Size | 100SHS 2' 8 Sash/Panel, Glass / Grile | Insect Scree SHGC EN | 0.31 | | VATURE | * All graphics as viewed from the exterior. ** Rough opening dime or flashings or slil panning or brackets or fasteners or other ltems. Thank you for choosing Andersen Windows & | |
| | | | a | U-Factor | 0.3 0 | | CUSTOMER SIGNATURE | phics as view ngs or sill par ik you for | |
| | | | | # thun | 14 | | CUSTC | - All gra or flash | |

| | \$2,084.84 | | White Exterior | | | Ext. Price | \$ \$611.45 | | ame, White Argon Fill taintess Glass / | | | \$9,471.01 \$0.00 \$0.00 \$615.62 | \$10,086,63 | |
|----------|---------------|---------------------------|--|---|---------|------------|---------------|-------------------------------|--|---|---------|--|-------------|---------------|
| AND TANK | \$521.21 | | Nite Exterior Frame. Standard Argon Fi Fiberglass | Comments: | | Unit Price | \$611.48 | | ., White Exterior Fra ne Low-E Standard te, 3/4° Grille Bar, S ass | Comments: | | SUB-TOTAL: FREIGHT: LABOR: TAX: | TOTAL | DATE |
| | None Assigned | | 100SHS Z' 8 1/2*X6' 9", Unit, 100 Serles Single-Hung, Reverse Cottage/Oriel, 1 3/8" Setback, White Exterior Frame, White Exterior Sash/Panel, Fixed/Active, Dual Pane Low-E Standard Argon Fill Stainless Glass / Grille Spacer, Auto Lock, Andersen 100 Serles, 1 Sash Looks White, Haif Screen, Fibérglass | | 5.05540 | Location | None Assigned | 9 1/2" | 100SHS 2' 8 1/2''X7' 5 1/2''. Unit, 100 Series Single-Hung, Reverse Cottage/Orial, 1 3/8'' Settback, Whitle Exterior Frame, White Exterior Frame, White Exterior Sash/Panel, Ked/Active, Dual Pane Low-E Standard Argon Fil Finelight Grilles-Between-the-Glass 2 Wide, 1 High, Specified Equal Light Pattern, White, wWhite, 3/4'' Grille Bar, Stainless Glass / Grille Spacer, Auto Lock, Andersen 100 Series, 1 Sash Locks White, Haif Screen, Fiberglass | Fiberglass White Area (Sq. Ft) Col | 5,62600 | | | |
| | | Unit Size = 32 1/2" x 81" | Cottage/Orie Fixed/Act Locks White | talf Screen Fl Height | 25.1027 | | | Unit Size = 32 1/2" x 89 1/2" | erse Cottage Sash/Panel, F Equal Light P White, White, | 5 Half Screen Height | 27.9360 | | | |
| | tive | Unit Size = | Hung, Reverse arior Sash/Pan Series, 1 Sash | HS 32.5 x 81 H Width | 29.0000 | UO | tive | Unit Size : | gle-Hung, Rev Vhite Interior S gh, Specified I 1 Sash Locks | HS 32.5 x 89.5 Width | 29.0000 | | | |
| | Fixed/Active | | 00 Serles Single-F rame, w/White Inte k, Andersen 100 S | Insect Screen 1: 100 Series Single-Hung, 100SHS 32.5 x 81 Half Screen Fiberglass White C ENERGY STAR Clear Opening/Unit # Width Height Area (Sq. FI) | A1 | Operation | Fixed/Active | | nt, 100 Series Sing Interior Frame, w/V Glass 2 Wide, 1 Hi srsen 100 Series, 1 | Insect Screen 1; 100 Series Single-Hung, 100SHS 32.5 x 89.5 Half Screen Fiberglass White C ENERGY STAR Clear Opening/Unit # Width Height Area (Sq. Ft) 1 | A1 | | | |
| ATA A | 4 | RO Size = 33" x 81 1/2" | MVMhite Interior F WVMhite Interior F Spacer, Auto Loo | an 1: 100 Series S VERGY STAR Cle | ON | Otv | ۲ | RO Size = 33" x 90" | 1 1/2"X7" 5 1/2". Ur htPanel, w/White I lles-Between-the- r, Auto Lock, Ande | en 1: 100 Series S VERGY STAR Cle | QN | | | |
| ITEL | 400 | RO Size: | 100SHS 2' 8 Sash/Panel, Glass / Grille | Insect Scree SHGC EN | 0.31 | Item | 500 | RO Size | 100SHS 2' 8 Exterior Sas Finelight Gri Grille Space | Insect Screet SHGC EN | 0.28 | | | SNATURE |
| l | C | | 3 | U-Factor | 63 | | | | 13 | U-Factor | 6.0 | | | CUSTOMER SIGN |
| | | | - | # #U | AT | | | | _ | # HUD | F | | | CUST |

| | Item | AD DA | | Operation | | Location | ONL FIGS | |
|----------------------|---|---|---|--|--|--|--|--|
| | 800 | 1 0 | Fixed | Fixed/Active | | None Assigned | d \$611.48 | \$611.48 |
| _ | ROS | RO Size = 33" x 90" | | Unit Size = 32 1/2" x 89 1/2" | = 32 1/2" x 8 | 9 1/2 ^m | | |
| Until# U-Factor | SHO | S 2' 8 1/2"X7' 5 SashParel, v ti Grilles-Betwe pacer, Auto Lo Screen 1: 100 ENERGY S' | 100SHS 2' 8 1/2' X7' 5 1/2' Unit, 100 Series Single-Hung, Reverse Cottage/Oriel, 1 3/8' Setback, Wh Exterior Sash/Pariel, w/White Interior Frame, w/White Interior Sash/Pariel, Fixed/Active, Dual Parie L Finelight Grilles-Between-the-Glass 2 Wide, 1 High, Specified Equal Light Pattern, While, w/White, 3/ Grille Spacer, Auto Lock, Andersen 100 Series, 1 Sash Locks White, White, Half Screen, Fiberglass Insect Screen 1: 100 Series Single-Hung, 100SHS 32.5.x 89.5 Half Screen Fiberglass White C ENERGY STAR Clear Opening/Unit # Width Height Area (Sq. Ft) Comme C | Single-Hung, Reve White Interior S 1 High, Specified E es, 1 Sash Locks V 00SHS 32.5 x 89.5 nit # Width | erse Cottage astivPanel, F squai Light P Mhite, White, Half Screen | /Onel, 1 3/8" Sett sted/Active, Dual attern, While, w/V , Half Screen, Fib Fiberglass White Area (Sq. Ft) | 100SHS 2 8 1/2"/ 5 1/2", Unit, 100 Series Single-Hung, Reverse Cottage/Oriel, 1 3/8" Setback, White Exterior Frame, White Exterior Sash/Panel, w/White Interior Frame, w/White Interior Sash/Panel, Fixed/active, Dual Pane Low-E Standard Argon Fill Finellight Grilles-Between-the-Glass 2 Wide, 1 High, Specified Equal Light Pattern, White, w/White, 3/4" Grille Bar, Stainless Glass / Grille Spacer, Auto Lock, Andersen 100 Series, 1 Sash Locks White, White, Half Screen, Fiberglass Insect Screen 1: 100 Series Single-Hung, 100SHS 32.5, 88.5 Half Screen Fiberglass White Externation Comments - Comments - | ne, White Argon Fill ainless Glas |
| A1 0.3 | 0.28 | N | A1 | 29.0000 | 27.9360 | 5,62600 | | |
| | Item | m Otv | | Operation | | Location | Unit Price | e Ext. Price |
| | 700 | | j | Fixed / Fixed/Active | | None Assigned | d \$888.15 | \$888,15 |
| B | RO Mull: Fa 100RE Equal 5 Specifik Sash Lu | RO Size = 33 1/4" x 102 3/4" III: Factory Mulleu, Nonreinforo OREC 27 8 1/2"X2' / 100SHS 2 ual Sash, 1 3/8" Setback, Whi it 1. Fixed/Active, Unll 2: Fixed ecified Equal Light Pattern, W sh Locks White, White, Half S | RO Size = 33 1/4" x 102 3/4" Mull: Factory Mulled, Nonreinforced John - Factory 100REC 2' 8 1/2"X2' / 100SHS 2' 8 1/2"X6' 5 1/2" Equal Sash, 1 3/8" Setback, While Exterior Frame, Unit 1. Fixed/Active, Unil 2: Fixed, Dual Pane Low Specified Equal Light Pattern, White, Withie, 3/4" Sash Locks White, White, Half Screen, Fiberglass | Unit Size: actory Assembled 5 1/2" Unit 1: Frame, White Exter e Low-E Standard Ia, 3/4" Grille Bar, I rglass | Unit Size = 32 1/2" x 102" usernbled Stack Mull, 1/2" unit, Unit 1: 100 Series Sing White Exterior Sash/Panel, Standard Argon Fill Fineli Grille Bar, Stainless Glass / | 02" 1/2" Fiberglass No Single-Hung. Unit nel, w/White Inter nelight Grilles-Bei sss / Grille Space | RO Size = 33 1/4" x 102 3/4" Unit Size = 32 1/2" x 102" Mult: Factory Mulled, Nonreinforced John - Factory Assembled Stack Mult, 1/2" Fiberglass Non Reinforced Honzontal Mull Material 100REC 2" 8 1/2"X2' / 100SHS 2" 8 1/2"X6' 5 1/2". Unit Unit 1: 100 Series Single-Hung. Unit 2: 100 Series Picture/Transom-SH. Equal Sash, 1 3/8" Setback, White Exterior Frame, White Exterior Sash/Panel, w/White Interior Frame, w/White Interior Sash/Panel, Unit 1. Fixed/Active. Unit 2: Fixed, Dual Pane Low-E Standard Argon Fill Finelight Grilles-Between-the-Glass 2 Wide, 1 High, Specified Equal Light Pattern, White, w/White, 3/4" Grille Bar, Stainless Glass / Grille Spacer, Auto Lock, Andersen 100 Series, 1 Sash Locks White, White, Half Screen, Fiberglass | Mull Materi ransom-SH, for Sash/Pa , 1 High, 100 Serles, |
| Unit # U-Factor | SHG | Screen 1, 100 ENERGY S | Insect Screen 1, 100 Series Single-Hung, 100SHS 32,5 x 77,5 Half Screen Fiberglass White C ENERGY STAR Clear Opening/Unit # Width Height Area (Sq. F1) | 00SHS 32.5 x 77.5 hill # Width | 5 Half Screer Height | n Fiberglass White Area (Sq. Ft) | a Comments: | |
| At 0.3 A2 0.27 | 0.28 0.29 | 92 | A1 | 0000.62 | 35,0390 | 7,05650 | | |
| | | | | | | | SUB-TOTAL FREIGHT: LABOR: TAX: TOTAL: | \$10,970.64 \$0.00 \$713,09 \$11,683.73 |
| DOLLATOMOD SICNATING | DONATIDE | | | | | | DATE | |

| Ruote 3491164 | test Delivery Data 3/24/2023 |
|--|----------------------------------|
| RUOTO 34571104 E Seria latest delivery dates are not accurately reflecte | |
| | Date: 2/13/2023 1.41:06 P |
| | ly at this time, subject to chan |
| 10 | |
| LU . | |
| Consistence: 000552 9 1/2 s.dr/3.5.dr/1000522 8 1-2 s.dr. 2 s.dr. 1015 tigb Crossinet CV0 Palled Hot. | |
| 12.1./2.3.55.3.4. Enlarge Performance Fla. Carbon Steeds of Height - Caston Tanae Wells - 17.1/2 | |
| France Height - 50 374 Tridinated Drivenicas - RO 13 174 + 51 1722 [1010] 31 1725 - 50 1567 [1376] Saturd, Final Stylegicy Ent.2 Left Wave Edenie France Web Edenie Serf. Dated. A Web Heighte France. | Qty: 2 |
| w White one as sat/Direct Har. Jon: 1 Sergeneil Argon File Fishers / Sinke Sprear) plant Stanlast Int Z. | Latest Delivery |
| travel, input Mult Shi s/ Eith "pour Gala" "Jundas Gills, Instehl, Specific Hope Split 751, 266, | Date: |
| Write 2WH () lardware Tolding, 1 Schlurk, Write Lut, Window Opening Corrol Desired In. Homenkoved. | 0.004/2023 |
| Jan - repary Pyre doubt, 24r3, Mill Unit L Bre CPU Number - ANU Ni 84 02388 (2020). US briang Sim Unit | |
| [7] Un (CPD) Fordates - Ar ID-11-84.02444 (2004), T1ar115 Energy Size. H preparatel. Redexy Model 11/27 | |
| Fibrights From Reviolation 2: 87 2023, 4500 Centry 1:1 | |
| > Details | |
| · Lance | |
| 300 | |
| 100 C | |
| 100, 100 Single Hung Equal Sect. 32 172 e. 7, Education Robinson (1): 1-378' Sollar & het d/Active: Moto | Qty. |
| Laterse Lenne, With Educed Scale/Proof. White later a force set White later a Scale/Prior Later a Scale/Prior Later a Scale/Prior Later a Scale Prior Later a Scale Pr | Latest Delivery Date: |
| (3) NY Q dia Sprain Calm - Stimilias, Coldas Emilipit SpecTind Lenablisht, 37 # White, White 2WTH, Humboure Asia (ad. Lice Andersen 130 for an 1 Sech table, White (ock. Winear Opening Control Decise 11) | - 734 73092 |
| Twitter D Thanking ALID (180.02064-932.00, 116/11) Every Skin Yorion 279, 2023 | CHCR04 |
| | |
| Detain | |
| | |
| 900 | |
| Uni 1095 under Hung Equal Sud. 32 1/2 x 2 Eduance Potenzauer 7 to 1 3/8° Saliente Insed/Attan When | City 5 |
| Easters haves White Estered and /Right: White haves a White later is a White later in Sentr/Prinet loss is sugged likely | Latent Delivery |
| silasy 15the spicer Löhn = Semleys Collex Flore Himber 6 Ave led. Incl Anderen 100 Semi- Floreb | Date: |
| is die VShite Luck, Weisher Open ing Castal Downer LL. Buit (PDT heilen - AUD / 148) (12055/13070, 1140) | 175622021 |
| Compg (11) - Norman 2/B/2033 | |
|) Details | |
| - 2000 | |
| | |
| Line, 4637 Suglishing kerene Campe/Colel 32 1, 2 x 81, in parent for a procedure of the 1 J (9) Selperk | City: -1 |
| Free dy'netwo White Educe chornes, Alter Educes, Suid y Band, AMAR for the Frees, w/W atchterin Suid y Fords | Latost Dolivery |
| I con E. Jagen Hood Talency Table Sprices Collect Studius, Giller, Name Hundame, Amsterl. 1991 Burdoway 1991 | Date: |
| Series, 1 Sentrincks, White text, Windows, Seering Center Division For, 1041, 701 Hauther - AFID F1 80, 02(189 | 175472023 |
| (2000), (HaltDS Imagy Viz., Sneven 2/6/2020) | |
| | |
| > Decisile | |

Lead times displayed acave are exeminated and the opportunity to quote Andersen Windows and Deers!

Champion Estimate-

| | | FIEI | LD WORK ORDER |
|--------------------------|--------------------|----------|---------------|
| Name Shaws Hemans | Phone (347) 476 09 | 80 | Date 2(9) 23 |
| Address 10 Kirk Are | city Hamilton | State OH | Zip 4501 |
| Factory Rep Charles Rowe | | | |

| BSM Basement | F Fayer | LR Living Room | | DH Double-Hung | 2P Silder | COLOR | D White | 🗆 Tan |
|----------------------------|--------------------------|-------------------------|-----------------------|---|---------------------|-------------|---------|-------|
| BTR Bathroom BR Bedroom | GR Game Room G Garage | OFF Office S Surroom | BAY Bay BOW Bow | TWIN 2 DH + Mull HOP Hopper | 3P Slider - 3 Panel | ColorBond® | D Yes | D No |
| CI. Closet | K Kitchen | LR UNITY Room | CS Casement - Single | Contraction of the second s | | TimberBond® | D Yes | D No |
| D Den | L Library | 1 | CS2 Casement - Double | DHP Pitture w/ 2 DH Flankers | | - | | |

Mark TOP of box for Obscure, Grids, and Temper TOP Sash - BOTTOM of box for BOTTOM Sash

| | Location | Widt | h x Height | Total U I | Туре | Grid | Obs | Temp | Full Screens | Options | 1. | MSRP | |
|----|----------|--------|------------|--------------|------|------|-----|------|-----------------|-------------|------|------|-----|
| 1 | Front | 34 | ×102 | | đH | - | | | | \$ 3,984.00 | Perw | MOON | |
| 2 | 1 | 1 | × | | | - | - | | | | _ | | |
| 3 | | | ×. | | | - | | | | | | | |
| 4 | | | × | | | - | | | | | | | |
| 5 | 1 | \sim | × | | | - | | | | | | | _ |
| 6 | | | × | | | - | | | | | F | 1 | 1 |
| 7 | 1 | | × | | | - | | | | 1 | | _ | 11 |
| 8 | | | ж | | | - | | | | | | - | 11 |
| 9 | | | × | | | - | | | 0 | | F | - | 102 |
| 10 | | | × | | | - | | | | | | | 1 |
| 11 | | | ж | | | - | 1 | - | | | | | |
| 12 | | | × | | | - | | | | | L | 1 | 1. |
| 13 | | | × | | | - | | | | | 4 | 34"- | • |
| 14 | | | x | | | - | | | | | 2 | | |
| 15 | | | × | | | - | | - | | | | | |
| 16 | | | x | | | - | | - | 1 | | | | |
| 17 | | | х | | | | | | | | | | |
| 18 | | | x | | | - | | | | | | | |
| 19 | | 1 | х | | | - | | | | | | | |
| 20 | | | х | | 1 | - | | - | | | | | |

Downstairs Front

Upstairs Front

FORM INFO7-0614" COmmpton=, 2014

Infinity From Marvin Estimate-

Dani Baxter <dani.baxter@hamilton-oh.gov>

Fwd: Fw: Size Restrictions 1 message

Liz Hayden <liz.hayden@hamilton-oh.gov> To: Dani Baxter <dani.baxter@hamilton-oh.gov> Fri, Feb 3, 2023 at 9:31 AM

From: hwspropertygroupinc@yahoo.com <hwspropertygroupinc@yahoo.com> Date: Thu, Feb 2, 2023 at 6:43 PM Subject: Fw: Size Restrictions To: Liz Hayden <liz.hayden@hamilton-oh.gov>

Hi Liz,

See email below from Michael Schackmann Marvin Product line.

Sent from Yahoo Mail on Android

Forwarded Message -- From: "Michael Schackmann" <Michael.Schackmann@infinityfrommarvin.com>
 To: "hwspropertygroupinc@yahoo.com" <hwspropertygroupinc@yahoo.com>
 Sent: Thu, Feb 2, 2023 at 2:43 PM
 Subject: Size Restrictions
 Hello, Shawn.
 As much as I would like to eam your business, I am afraid that I won't be able to help you.
 While Infinity From Marvin Makes the strongest frame in the industry using our Ultrex Fiberglass, the maximum height we can make is 96". This is not due to the strength of the frame, but the capability of the various operating hardware, such as the lift and balance mechanism.
 If you are able to get approval from the City of Hamilton to use other configurations for the widow openings, please let me know and would be happy to discuss options and provide you with an accurate estimate.

Infinity from Marvin - Checkinati C: 513.919.2585 | michael.schackmann@infinityfrommarvin.com

Scofield Estimate-



ORDER: 117576 ORDER DATE: 2/13/2023 ORDER CONTACT:

QUOTE

INVOICE INFORMATION

SCOFIELD, L. E. WINDOW & DOOR 27-10219000 315 SOUTH B STREET HAMILTON, OH 45013 PH: 513.863.8932 FX: 513.383.3248 SHIPPING INFORMATION

SCOFIELD, L. E. WINDOW & DOOR 27-10219000 315 SOUTH B STREET HAMILTON, OH 45013 PH: 513.863.8932 FX: 513.383.3248

SHIP VIA:

| OF | DER | ORDER | DATE | PC | NUMBER | t | | CUSTOMER R | REF | TERMS | 1 |
|------|------------------------------------|------------------------------------|-----------------|-------|--------|-----|----|--------------------------------|---------------------|---------------------|---|
| | 7576 | 2/13/2 | | | | | | SCOFIELD / HEN | | | |
| IEN. | | DE | SCRIPTI | ON | - | QTY | | SIZE | PRICE | TOTAL | - |
| 1 | Factory Hold To Head E: | xpander d Sill Trim (4 | | | | 2 | 32 | 1/2 W X 102 H | \$845.54 | \$1,691.08 | Ħ |
| 11 | LillingW/e | ld 8420 Dou | ble Hund | | | 2 | 32 | ITEM SUBTOTAL: 1/2 W X 84 H | \$845.54 | \$1,691.08 | |
| 1.1 | Hold To | | iole riony | | | | 96 | 1/2 1/ / 04 11 | | | |
| | Half Scr | creen Frama oen iss Screen M | | | | | | | \$416,95 | \$833,90 | |
| | Suprem | e(2) | | | | | | | \$45.34 | \$90.68 | |
| | Bottom | Temper by Temper{Ten | Sash npered} | | | | | | \$58,13 | \$116.26 | |
| | Double | onial=[0H1V Locks Mull=[A] | 1 | | | | | | \$27.90 | \$55.80 | |
| | UF | SHGC | VT | AL | Zona | | | | | | |
| | 0.3 | 0.26 | 0.47 | 50.3 | NC | | | | | | |
| 1.2 | UltraWe | d 8400 Pict | ure Wind | ow. | | 2 | 32 | 1/2 W X 18 H | | | |
| | Hold To White Suprem Flat | Size | | 6 | | | | ALL ALL ATCH | \$193.75 \$19.76 | \$387.50 \$39.52 | |
| | Flat Col | onial=[0H1V Mull=[A] | 1 | | | | | | \$25.58 | \$51.16 | |
| | UF | SHGC | VT | AL | Zone | | | | | | |
| | 0.27 | 0,28 | 0.52 | ≤ 0.3 | N,NC | | | | | | |

2/13/2023 1:42:19 PM

1 6/4

| | 17576 | 2/13/3 | | | | | | SCOFIELD / HEM | | -1120300 | |
|-----|-------------------------------|--|-------------|-------|------|------|----|----------------|----------|------------------------|---|
| TEM | | | ESCRIPTI | | | Q1LA | | SIZE | PRICE | TOTAL | |
| 1.3 | | < Factory Si Mull=[A] | td. Mullion | | | 2 | 32 | 1/2 W | \$58.13 | \$116.26 | |
| 2 | Hold To Head Ex | ld 8420 Do Size kpander d Sill Trim (| | 1 | | 3 | 32 | 1/2 W X 72 H | | | F |
| | White Alum, Se Half Scr | creen Fram | ne (Std) | | | | | | \$383.63 | \$1,150.89 | |
| | Supreme | | in resource | | | | | | \$40.69 | \$122.07 | |
| | Flat Flat Cold Double I | onial=[0H1\ Locks | vi | | | | | | \$27.90 | \$83.70 | |
| | UF | SHGC | VT | AL | Zone | | | | | | |
| | 0.3 | 0.26 | 0,47 | \$0,3 | NG | | | | | | |
| | | | | | | | | ITEM SUBTOTAL: | \$452.22 | \$1,356.66 | |
| | Half Scre | ss Screen M e(2) | | | | | | | \$44.18 | \$1,667.80 \$176.72 | |
| | UF | SHGC | Vr I | AL | Zone | | | | | | |
| | 0,3 | 0.29 | 0.52 | €0.3 | NC | | | | | | |
| | | | - | | | | | ITEM SUBTOTAL: | \$461.13 | \$1,844.52 | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |

| OR | DER | ORDER | DATE | PC | NUMBER | | CUST | OMER REF | 1000 | TERMS | ă - |
|----|---|--|-----------------|-------------|---------|-----|-----------------|--|--|------------------------|------------------------------|
| 11 | 7576 | 2/13/2 | 023 | | | | SCOFIE | LD / HEMAN | VS | | |
| EM | Concession in which the | DE | SCRIPTI | DN. | | QTY | SIZE | | PRICE | TOTAL | - |
| 4 | UltraWel Hold To Head Ex Standard White Alum, So Half Scr | kpander d Sill Trim (4 creen Frame een ss Screen M e(2) | 156) e (Std) | AL \$0.3 | Zone | 6 | 32 1/2 W X 72 H | | \$383.63 \$40.69 | \$2,301.78 \$244.14 | |
| | 0,3 | 0.29 | 0.52 | \$1.3 | Inc. | | ITEM SUB | TOTAL: | \$424.32 | \$2,545.92 | |
| - | _ | | | | TOTALS: | 15 | | | SUBTOTAL: OHIO 5.75%: UTLER CNTY | \$ | 7,438.1 \$427.7 \$55.7 |
| | | GNATURE R | counce | | | | | 11 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 | 0.75%: | | |

COMMENT:

2/13/2023 1:42:19 PM

3 of 4




Exhibit E – Notice of Violation letter delivered January 13, 2023



Planning Department 345 High Street, 3rd floor Hamilton, Ohio 45011

January 12, 2023

HWS Property Group Inc 10 Kirk Ave Hamilton OH 45011

RE: Work Without a Certificate of Appropriateness (COA), Failure to Comply with ADRB Guidelines Regarding the Installation of Vinyl Windows and Doors –10 Kirk Ave, Hamilton Ohio 45011 – Parcel Number P6441025000003

To Whom it May Concern,

According to the records of the Butler County Auditor's Office you are the owner of the above referenced property.

10 Kirk Ave is noted as a Historic Structure and is subject to Section 2600 of the Hamilton Zoning Ordinance (HZO) whereby according to Section 2603 of the Hamilton Zoning Ordinance all structures contained within the locally registered Architectural Conservation/Historic are designated as having historic significance and/or character.

HZO Section 2603 Architectural Conservation/Historic Districts And Structures – Local Inventory of Structures Outside of Districts: Structures both inside and outside of the districts may be identified by the inventory map created by the Miami University Cartography Laboratory for the City of Hamilton Planning Department circa 1986. Individual properties subsequently designated by the ADRB and City Council as having architectural and/or historic significance can be added or deleted to this list based on the rules stipulated in 2630. The structures listed on this inventory will be under the purview of the ADRB.

HZO Section 2610 Certificate of Appropriateness: No alteration, painting, design change, color change, construction, reconstruction, erection, removal or exterior work on a structure, and no construction, erection, mounting, painting, design change, color change, moving, removal, or revision of permanent signage to any property in an Architectural Conservation/Historic District where such action or work will affect the exterior architectural and/or historic features or appearance of a structure, site, monument, streetscape, or neighborhood shall be permitted unless and until a Certificate of Appropriateness for such action or work has been applied for and issued by the Architectural Design Review Board, its Secretary, or Chairperson, as authorized by said Architectural Design Review Board.

The City will stay enforcement action against you until January 25, 2023, in order to afford you a final opportunity to comply with the zoning regulations. <u>The City demands that you cease work on the property immediately. You must apply for and pay all fees associated with a Certificate of Appropriateness through the Architectural Design Review Board.</u> Failure to comply may result in enforcement action against you, which may include filing civil or criminal actions against you in court.



Planning Department 345 High Street, 3rd floor Hamilton, Ohio 45011

4007 Election of Remedies/Penalties:

Whenever a person, firm or corporation violates or fails to comply with any of the provisions of this Zoning Ordinance No. 7503, the Planning Director or Designee shall have the authority to impose a penalty. The Planning Director or Designee may in conjunction with the City Law Director or his or her designee, pursue misdemeanor criminal charges pursuant to Section 4006 A), or pursue civil court action pursuant to Section 4006 B), or both, , against any person, firm or corporation who violates, disobeys, omits, neglects, or fails to comply with any of the provisions of this Zoning Ordinance No. 7503, and all amendments thereto, or who fails to comply with a notice of violation, stop work order, or any other order issued under this Zoning Ordinance No. 7503.

The Planning Director or Designee may pursue additional legal or equitable remedies, including injunctive relief, as necessary to enforce the provisions of this Zoning Ordinance No. 7503.

- A. Misdemeanor Offenses: Any person, firm or corporation who violates any provision of this Zoning Ordinance or knowingly violates a stop work order issued pursuant to Section 4001. (B) of this Zoning Ordinance No. 7503, shall be guilty of a unclassified misdemeanor and shall be fined not less than Five Hundred Dollars (\$500.00) or more than One Thousand Dollars (\$1,000.00) for each offense. Each day that a violation is permitted to exist shall constitute a separate offense. In addition to the penalties outlined in this Section 4505 A), a court may order a person, firm or corporation to correct the violation, if possible, and to make restitution for any property damage caused by the violation.
- B. Civil Action: The Planning Director or his or her Designee may file or pursue a civil action for injunctive relief to obtain compliance with any order issued under this Zoning Ordinance No. 7503 or for any other legal or equitable relief available, Any action pursued under this section may result in a judgment against the person, firm, or corporation that has violated this Zoning Code and lead to subsequent collection proceedings, including but not limited to foreclosure. The City may, at its option, elect to not utilize the procedure provided in this chapter, and proceed instead with the filing of a civil action in common pleas court in accordance with Ohio Revised Code Chapter 3767, Ohio Revised Code Chapter 715, or any other appropriate section of the Ohio Revised Code or this Zoning Code.

Contact the City of Hamilton Planning Department at 513-785-7350 if you have any questions concerning this information. Thank you in advance for your cooperation in this matter.

Sincerely,


Liz Hayden Director of Planning liz.hayden@hamilton-oh.gov 513-785-7068





Exhibit F – Ohio Historic Inventory Sheet

| 9. Coordinates Lat. Long. U.T.M. Reference 11. (1) 7 1 2 0 4 3 9 9 0 Zone Easting Northing 10. Site Structure Description of Structure Description of Important Features The simple front facade is marked by 2/2 windows with plain 1 and lugsills. The entrance has a transom and plain rectangul lintel. There are cornice returns on the side gable ends. T chimneys, both stuccoed, rise from each end of the roof. A r porch area on the west side has chamfered posts and a cement floor. 42. History and Significance 43. History and Significance 44. Description of Environment and Outbuildings A small frame garage is located at the rear. A cement found outbuilding is adjacent to this garage. Most of the homes n century. The city limits are nearby to the east, beyond whi | 4. Present Name(s) | | R |
|---|---|--|------------|
| 3. Location of Negatives Hamilton Planning Dept. John Kirk Residence 6. Specific Location 1425 High Street John Kirk Residence 7. City or Town Hamilton If Rural, Township & Vicinity Hamilton 16. Themaic Category Agriculture/Transportati 17. Delay of Period ca. 1850 7. City or Town Hamilton If Rural, Township & Vicinity Hamilton 16. Style or Design Federal 8. Sile Plan with North Arrow N 9. Coordinates N Lat. Long. U.T.M. Reference N 10. Sile D Sile Concertinates Structure Lat. Long. U.T.M. Reference Pice 11.0 National Yes Structure 13. Part of Estab. Yes O 14. District Yes O 14.3. Distr. No S 15. Name of Established District No 24. Further Description of Important Features The simple front facade is marked by 2/2 windows with plain 1 and lugsills. The entrance has a transom and plain rectangul lintel. There are cornice returns on the side gable ends. T chimmeys, both stuccoed, rise from each end of the roof. A r porch area on the west side has chamfered posts and a cement floor. 24. History and Significance Although this building's nineteenth century residents are not that they were probably engaged i | | | Bur- 1 |
| Hamilton Planning Dept. Joint KITK Restdence 6. Specific Location 1425 High Street 1425 High Street 17. Date(s) or Period ca. 1850 7. Gity or Town If Rural, Township & Vicinity Hamilton 18. Street 8. Sile Plan with North Arrow N 9. Coordinates N Lat. Long. UTM. Reference N 10. Therefore Residential 23. Owner's Name & Address. 11. Onstional Yes D 12. Site Contact Person or Organizati Hamilton Planning Dept. 2. Further Description of Important Features 23. Open to Public? 2. Further Description of Important Features 24. Owner's Name & Address. The simple front facade is marked by 2/2 windows with plain 1 and lugsills. The entrance has a transom and plain rectangul lintel. There are cornice returns on the side gable ends. T chinneys, both stuccoed, rise from each end of the roof. A r porch area on the west side has chamfered posts and a cement floor. 3. History and Significance Although this building's nineteenth century residents are not that they were probably engaged in agricultural activities du of the surroundings, The 1927-28 Hamilton City Directory did for this side of the street, but in 1931, John Kirk, an autom 4. Description of Environment and Outbuildings A small frame garage is located at the rear. A cement found outbuilding is adjacent to this garage. Most of t | CALCULATION OF A CONTRACT OF A CONTRACT OF A CONTRACT OF A | bir do bolake (bewirteda) | 759-9 |
| 1425 High Street Agriculture/Transportation 17. Date(s) or Period ca. 1850 27. City or Town If Rural, Township & Vicinity Hamilton 18. Style or Design Federal 18. Sile Plan with North Arrow N 19. Architect or Engineer 20. Contractor or Builder 21. Original Use, If apparent Residential 22. Present Use Residential 22. Owner's Name & Address, If known Priod 24. Owner's Name & Address, If known Priod 25. Open to Building S Object 26. Local Contact Person or Organizati Hamilton Planning Dept. Register? No S 27. Further Description of Important Features The simple front facade is marked by 2/2 windows with plain 1 and lugsills. The entrance has a transom and plain rectangul lintel. There are cornice returns on the side gable ends. T chinneys, both stucced, rise from each end of the roof. A report area on the west side has chamfered posts and a cement floor. 27. History and Significance Although this building's nineteenth century residents are not that they were probably engaged in agricultural activities du of the surroundings., The 1927-28 Hamilton City Directory did for this side of the street, but in 1931, John Kirk, an autom outbuilding is adjacent to this garage. Most of the homes n century. The city limits are nearby to the east, beyond whi | John Kirk Residence | is an exacted at a | è |
| 17. Date(a) or Period (a) 1850 (b) 19. Director 18. Architect or Engineer (c) 19. Architect or Engineer 19. Architect or Engineer 19. Architect or Engineer 20. Contractor or Builder 21. Original Use, if apparent Residential 22. Present Use Residential 23. Owner's Name & Addrese, (c) 71. 71. 71. 2.0 (c) 71. 71. 72.0 (c) 71. 71. 71. 72.0 (c) 72.0 (c) 72.0 (c) 72.0 (c) 72.0 (c) 72.0 (c) 72.0<td></td><td>28. No. of Stories 2-1/2</td><td>P</td> | | 28. No. of Stories 2-1/2 | P |
| 26. 1850 27. City or Town H Rural, Township & Vicinity Hamilton 18. Stile Plan with North Arrow 3. Sile Plan with North Arrow 19. Architect or Engineer 20. Contractor or Builder 21. Original Use, H apparent Residential 22. Present Use 23. Ownership 24. Owner's Name & Address, H Kown 25. Open to Building S 26. Coardinates 27. Cordinates 28. Par of Established District 29. Further Description of Important Features The simple front facade is marked by 2/2 windows with plain 1 and lugsills. The entrance has a transom and plain rectangul lintel. There are cornice returns on the side gable ends. T chimneys, both stuccoed, rise from each end of the roof. A r porch area on the west side has chamfered posts and a cement floor. 29. History and Significance Although this building's nineteenth century residents are not that they were probably engaged in agricultural activities du of the surroundings., The 1927-28 Hamilton City Directory did for this side of the street, but in 1931, John Kirk, an autom 4. Description of Environment and Outbuilding A small frame garage is located at the rear. A cement found outbuilding is adjacent to this garage. Most of the homes n century. The city limits are nearby to the east, beyond whi | | | Butler |
| Hamilton Federal 3. Sile Plan with North Arrow N 3. Sile Plan with North Arrow N 4. Orginal Use, If apparent Residential 20. Contractor or Builder 2. Coordinates Lat. Long. Lat. Long. Northing 0. Sile O Structure O Public? 28. Open to Public? Solution Public? 28. Local Contact Person or Organizati Hamilton Planning Dept. Pichil? 29. Open to Public? 20. Other Surveys in Which Included 19. Part of Estab. Yes O 14. District Yes O Hist Dist.? No B Potenti? No X 3. Name of Established District 27. Other Surveys in Which Included 29. Further Description of Important Festures The simple front facade is marked by 2/2 windows with plain 1 and lugsills. The entrance has a transom and plain rectangul lintel. | | 30. Foundation Material | R |
| Site Plan with North Arrow Site Plan with North Arrow High High Architect or Engineer Coordinates Coordinates Lat. Long. U.T.M. Reference U.T.M. Reference I 7 1 4 7 20 U.T.M. Reference I 7 1 4 7 1 20 U.T.M. Reference I 7 1 4 7 1 20 U.T.M. Reference I 7 1 4 7 1 20 U.T.M. Reference I 7 1 4 7 1 20 U.T.M. Reference I 12. Is It Yes S Register? No S Part of Estab. Yes D Hist. Dist.? No S S. Name of Established District Yes S The simple front facade is marked by 2/2 windows with plain 1 and lugsills. The entrance has a transom and plain rectangul lintel. There are cornice returns on the side gable ends. T chimneys, both stuccoed, rise from each end of the roof. A r porch area on the west side has chamfered posts and a cement floor. A. History and Significance Although this building's nineteenth century residents are not that they were probably engaged in agricultural activities du of the surroundings., The 1927-28 Hamilton City Directory did for this side of the street, but in 1931, John Kirk, an autom outbuilding is adjacent to this garage. Most of the homes n century. The city limits are nearby to the east, beyond whi | | Stone | |
| High N 20. Contractor or Builder 21. Original Use, if apparent Residential 22. Present Use Residential 23. Ownership Coordinates Lat. Long. U.T.M. Reference [4] 7] 1 7 2 0 [4] 7 0 2 9 9 0 Dne Easting Dome Easting Site D Structure Digible? Duilding S Object D Part of Estab. Yes D 12. Is It Digible? Part of Estab. Yes D 14. District Yes D Hist. Dist.? No S Potenti? No S Potenti? No S Part of Estab. Yes D 14. District Yes D Hist. Dist.? No S Potenti? No S Potenti? No S Anme of Established District 27. Windows with plain 1 and lugsills. The entrance has a transom and plain rectangul lintel. There are cornice returns on the side gable ends. T chimneys, both stuccoed, rise from each end of the roof. A r porch area on the west side has chamfered posts and a cement floor. History and Significance | | 31. Wall Construction | 1 |
| High 21. Original Use, if apparent Residential 22. Present Use Residential 23. Ownership Pri Coordinates Lat. Long. U.T.M. Reference U.T.M. Reference Pri Description of Important Feestures Structure Public? 26. Local Contact Person or Organizati Hist. Dist.? No Ø Potenti? No Ø 27. Other Surveys in Which Included Part of Established District Potent?? No Ø 27. Other Surveys in Which Included Part of Established District Potent?? No Ø 27. Which Madding for the sture cornice returns on the side gable ends. T Chimeys, both stuccoed, rise from each end of the roof. A r porch area on the west side has chamfered posts and a cement floor.< | N | Brick load-bearing 32. Roof Type & Material | 1 |
| 21. Original Use, if apparent Residential 22. Present Use Lat. Long. U.T.M. Reference [4] 71 [4] 7] 2[0] [4] 3[2] 9[9] 0 Deme Easting Northing Dire Easting Building S Object On National Yes 12. Isit Period Eligible? Part of Estab. Yes 14. District Part of Estab. Yes 14. District Potenti? No S Name of Established District 27. Other Surveys in Which Included Part of Estab. Yes 14. District Yes Potent?? No S Name of Established District 27. Other Surveys in Which Included Protent?? No S Potent?? No S Name of Established District 27. Windows with plain 1 and lugsills. The entrance ha | 20. Contractor or Builder | Gable/asph. shing. | |
| Residential Residential Coordinates Lat. Long. U.T.M. Reference Pice Dividing SP Object On National Yes 12.1sit Yes SP Register? No SP Eligible? No Part of Estab.Yes 14. District Yes SP Potenti? No SP Hist. Dist.? No SP Potent?? No SP Potent?? No SP Potent?? No SP Courde a con the west side has chamfered posts and a cement floor. Arr porch area on the west side has chamfered posts and a cement floor. History and Significance Although this building's nineteenth century residents are not that they were probably engaged in agricultural activities du of the surroundings. The 1927-28 Hamilton City Directory did for this side of the street, but in 1931, John Kirk, an autom outbuilding is adjacent to this garage. Most of the homes n century. The city limits are nearby to the east, beyond whi | 21. Original Use, if apparent | 33. No. of Bays Front 3 Side 4 | |
| Residential Coordinates Lat. Long. Lat. Long. 23. Ownership Proving U.T.M. Reference U.T.M. Reference 24. Owner's Name & Address, if known Proving U.T.M. Reference U.T.M. Reference 25. Open to Public? Dre Easting Northing 25. Open to Public? Site O Structure O Public? On National Yes O 12. Is It Yes Z Provinting Dept. Part of Estab. Yes O 14. District Yes O Potentin No X Potentin No X Part of Established District 14. District Yes O Potentin No X Potentin No X P. Further Description of Important Features The simple front facade is marked by 2/2 windows with plain 1 and lugsills. The entrance has a transom and plain rectangul lintel. There are cornice returns on the side gable ends. T chinneys, both stuccoed, rise from each end of the roof. A r porch area on the west side has chamfered posts and a cement floor. Mistory and Significance Although this building's nineteenth century residents are not that they were probably engaged in agricultural activities du of the surroundings., The 1927-28 Hamilton City Directory did for this side of the street, but in 1931, John Kirk, an autom outbuilding is adjacent to this garage. Most of the homes n century. The city limits are nearby to the east, beyond whi | Residential | 34. Wall Treatment | |
| 23. Ownership Pu Lat. Long. U.T.M. Reference U.T.M. Reference U.T.M. Reference IIII I I I I I I I I I I I I I I I I I | | Common bond brick | |
| Coordinates Print Lat. Long. U.T.M. Reference IIII [7] [2] [2] [2] [2] [2] [2] [2] [2] [2] [2 | | 35. Plan Shape L 36. Changes Addition | 1 |
| Let. Long. U.T.M. Reference U.T.M. Reference Building S Northing Northing Dist Dist Dist District Yes D Register? No S Eligible? No D Part of Estab. Yes D 14. District Yes D Hist. Dist.? No B Potent'!? No S S. Name of Established District Potent'!? No S C. Further Description of Important Features The simple front facade is marked by 2/2 windows with plain 1 and lugsills. The entrance has a transom and plain rectangul lintel. There are cornice returns on the side gable ends. T chimneys, both stuccoed, rise from each end of the roof. A r porch area on the west side has chamfered posts and a cement floor. B. History and Significance Although this building's nineteenth century residents are not that they were probably engaged in agricultural activities du of the surroundings., The 1927-28 Hamilton City Directory did for this side of the street, but in 1931, John Kirk, an autom Description of Environment and Outbuildings A small frame garage is located at the rear. A cement found outbuilding is adjacent to this garage. Most of the homes n century. The city limits are nearby to the east, beyond whi | Private | S (Explain Altered D | ١. |
| U.T.M. Reference [6] 7111720 4720790 Image: Construction of the structure of the surroundings. Northing Done Easting Northing Done Easting Northing Done Easting Northing Done Estable Structure of Delect Building S Object 26. Local Contact Person or Organization Hamilton Planning Dept. 26. Local Contact Person or Organization Part of Estab. Yes 14. District Yes protection 27. Other Surveys in Which Included Part of Established District Potent17 No \$ 27. Other Surveys in Which Included Part of Established District Potent17 No \$ 27. Windows with plain 1 and lugsills. The entrance has a transom and plain rectangul lintel. There are cornice returns on the side gable ends. T chimneys, both stuccoed, rise from each end of the roof. A r porch area on the west side has chamfered posts and a cement floor. 28. History and Significance 21. History and Significance Although this building's nineteenth century residents are not 100 the surroundings., The 1927-28 Hamilton City Directory did for this side of the street, but in 1931, John Kirk, an autom | | in #42) Moved | 1 |
| Date Easting Northing Building S Structure Object Con National Yes 12. Is It Yes S Register? No Z Eligible? Part of Estab. Yes 14. District Yes Potent1? Hist. Dist.? No Z Potent1? No X S. Name of Established District Potent1? No X Z Part of List. Yes 14. District Yes Potent1? No X S. Name of Established District Potent1? No X Part of List. Yes Potent1? No X S. Name of Established District Potent1? No X Potent1? No X S S S. Name of Established District Potent1? No X Potent1? No X S S Register, No X The entrance has a transom and plain rectangul lintel. There are cornice returns on the side gable ends. T chimneys, both stuccoed, rise from each end of the roof. A r porch area on the west side has chamfered posts and a cement floor. B. History and Significance Although this building's nineteenth century residents are not that they were probably engaged in agricultural activities du of the surroundings., The 1927-28 Hamilton City Directory did for this sid | | 37. Condition Interior | |
| Site Structure Public? Building S Object 26. Local Contact Person or Organizati An National Yes 12. Is it Yes S Register? No Z Eligible? No Part of Estab. Yes 14. District Yes S Potent'l? No X 27. Other Surveys in Which Included Part of Estab. Yes 14. District Yes Potent'l? No X 27. Other Surveys in Which Included Part of Established District Potent'l? No X 27. Other Surveys in Which Included Part of Established District Potent'l? No X 27. Other Surveys in Which Included Part of Established District Potent'l? No X 27. Other Surveys in Which Included Part of Established District Potent'l? No X 27. Other Surveys in Which Included Part of Established District Potent'l? No X 27. Other Surveys in Which Included Part of Established District Potent'l? No X 27. Other Surveys in Which Included Part of Established District Potent'l? No X 27. Other Surveys in Which Included Part of Established District Potent'l? No X 27. Potent'l? Part of Established District Potent'l? No X Intel . There are cornice return | | Exterior Good | |
| Building S Object 28. Local Contact Person or Organizati On National Yes 12. Is It Yes S Register? No S Eligible? No C Part of Estab. Yes D 14. District Yes D Potent'? No X Hist. Dist.? No S Potent'? No X Name of Established District Potent'? No X Protection of Important Features Potent'? No X Name of Established District Potent'? No X Protection of Important Features Potent'? No X Name of Established District Potent'? No X No Heat Stable Protection of Important Features Potent'? The simple front facade is marked by 2/2 windows with plain 1 and lugsills. The entrance has a transom and plain rectangul lintel. There are cornice returns on the side gable ends. T potent'? chimmeys, both stuccoed, rise from each end of the roof. A r porch area on the west side has chamfered posts and a cement floor. History and Significance Potent'? P | Dublian | | 1 |
| On National Yes 12. Is it Yes & Eligible? No Hamilton Planning Dept. Part of Estab.Yes 14. District Yes 77. Other Surveys in Which included Part of Estab.Yes 14. District Yes 77. Other Surveys in Which included Part of Estab.Yes Potent'? No 77. Other Surveys in Which included Part of Established District Potent'? No 77. Other Surveys in Which included . Name of Established District Potent'? No 77. Other Surveys in Which included . Name of Established District Potent'? No 77. Other Surveys in Which included . Name of Established District Potent'? No 77. Other Surveys in Which included . History and Significance The entrance has a transom and plain rectangul 11. There are cornice returns on the side gable ends. The porch area on the west side has chamfered posts and a cement floor. . History and Significance Although this building's nineteenth century residents are not the they were probably engaged in agricultural activities du of the surroundings., The 1927-28 Hamilton City Directory did for this side of the street, but in 1931, John Kirk, an autom . Description of Environment and Outbuildings A small frame garage is located at the rear. A cement found outbuilding is adjacent to this garage. Most of the homes n century. | Structure D | 39. Endangered? Yes | |
| Hegister/ No B Englote/ No L Part of Estab. Yes D 14. District Yes D Potenti? No X Hist. Dist.? No B Potenti? No X S. Name of Established District Potenti? No X Part of Established District Potenti? No X Part of Established District Potenti? No X Provide the simple front facade is marked by 2/2 windows with plain 1 and lugsills. The entrance has a transom and plain rectangul lintel. There are cornice returns on the side gable ends. T chimneys, both stuccoed, rise from each end of the roof. A r porch area on the west side has chamfered posts and a cement floor. P. History and Significance Although this building's nineteenth century residents are not that they were probably engaged in agricultural activities du of the surroundings., The 1927-28 Hamilton City Directory did for this side of the street, but in 1931, John Kirk, an autom Description of Environment and Outbuildings A small frame garage is located at the rear. A cement found outbuilding is adjacent to this garage. Most of the homes n century. The city limits are nearby to the east, beyond whi | It Yes Z Hamilton Planning Dept. | By What? No 2 | Ŀ |
| Hist. Dist.? No (2) Potent'? No (2) Putner of Established District Important Features The simple front facade is marked by 2/2 windows with plain 1 and lugsills. The entrance has a transom and plain rectangul lintel. There are cornice returns on the side gable ends. The chimneys, both stuccoed, rise from each end of the roof. A reporch area on the west side has chamfered posts and a cement floor. History and Significance Although this building's nineteenth century residents are not that they were probably engaged in agricultural activities du of the surroundings., The 1927-28 Hamilton City Directory did for this side of the street, but in 1931, John Kirk, an autom Description of Environment and Outbuildings A small frame garage is located at the rear. A cement found outbuilding is adjacent to this garage. Most of the homes n century. The city limits are nearby to the east, beyond white | 27. Other Surveys in Which Included | | |
| 2. Further Description of Important Features The simple front facade is marked by 2/2 windows with plain 1 and lugsills. The entrance has a transom and plain rectangul lintel. There are cornice returns on the side gable ends. T chimneys, both stuccoed, rise from each end of the roof. A r porch area on the west side has chamfered posts and a cement floor. 2. History and Significance Although this building's nineteenth century residents are not that they were probably engaged in agricultural activities du of the surroundings., The 1927-28 Hamilton City Directory did for this side of the street, but in 1931, John Kirk, an autom Description of Environment and Outbuildings A small frame garage is located at the rear. A cement found outbuilding is adjacent to this garage. Most of the homes n century. The city limits are nearby to the east, beyond whi | | 40. Visible from Yes X Public Road? No | Ł |
| The simple front facade is marked by 2/2 windows with plain 1 and lugsills. The entrance has a transom and plain rectangul lintel. There are cornice returns on the side gable ends. T chimneys, both stuccoed, rise from each end of the roof. A r porch area on the west side has chamfered posts and a cement floor. History and Significance Although this building's nineteenth century residents are not that they were probably engaged in agricultural activities du of the surroundings. The 1927-28 Hamilton City Directory did for this side of the street, but in 1931, John Kirk, an autom Description of Environment and Outbuildings A small frame garage is located at the rear. A cement found outbuilding is adjacent to this garage. Most of the homes n century. The city limits are nearby to the east, beyond whi | | 41. Distance from and | 1 |
| The simple front facade is marked by 2/2 windows with plain 1 and lugsills. The entrance has a transom and plain rectangul lintel. There are cornice returns on the side gable ends. T chimneys, both stuccoed, rise from each end of the roof. A r porch area on the west side has chamfered posts and a cement floor. History and Significance Although this building's nineteenth century residents are not that they were probably engaged in agricultural activities du of the surroundings. The 1927-28 Hamilton City Directory did for this side of the street, but in 1931, John Kirk, an autom Description of Environment and Outbuildings A small frame garage is located at the rear. A cement found outbuilding is adjacent to this garage. Most of the homes n century. The city limits are nearby to the east, beyond whi | | Frontage on Road | 1 |
| and lugsills. The entrance has a transom and plain rectangul lintel. There are cornice returns on the side gable ends. T chimneys, both stuccoed, rise from each end of the roof. A r porch area on the west side has chamfered posts and a cement floor. History and Significance Although this building's nineteenth century residents are not that they were probably engaged in agricultural activities du of the surroundings., The 1927-28 Hamilton City Directory did for this side of the street, but in 1931, John Kirk, an autom Description of Environment and Outbuildings A small frame garage is located at the rear. A cement found outbuilding is adjacent to this garage. Most of the homes n century. The city limits are nearby to the east, beyond whi | t Features | 30 | ⊢ |
| Although this building's nineteenth century residents are not that they were probably engaged in agricultural activities du of the surroundings. The 1927-28 Hamilton City Directory did for this side of the street, but in 1931, John Kirk, an autom Description of Environment and Outbuildings A small frame garage is located at the rear. A cement found outbuilding is adjacent to this garage. Most of the homes m century. The city limits are nearby to the east, beyond whi | rance has a transom and plain rectangular nice returns on the side gable ends. Two ad, rise from each end of the roof. A rece | tall ssed | James Kirk |
| that they were probably engaged in agricultural activities du of the surroundings. The 1927-28 Hamilton City Directory did for this side of the street, but in 1931, John Kirk, an autom Description of Environment and Outbuildings A small frame garage is located at the rear. A cement found outbuilding is adjacent to this garage. Most of the homes n century. The city limits are nearby to the east, beyond while | | | Res |
| A small frame garage is located at the rear. A cement found outbuilding is adjacent to this garage. Most of the homes n century. The city limits are nearby to the east, beyond whi | Ly engaged in agricultural activities due t The 1927-28 Hamilton City Directory did no | o the rural nature t list addresses | Residence |
| | is located at the rear. A cement foundati ant to this garage. Most of the homes near | by are from the twentieth | |
| Sources of Information | | 48. Prepared by | |
| Williams' Hamilton City Directories | ty Directories | Rita Walsh | |
| | | 47. Organization Miami Purchase Ass'n | |
| | | 48. Date 49. Revision Date(s) | 1 |





| То: | Architectural Design Review Board |
|----------|--|
| From: | Dani Baxter |
| Subject: | Old Business - AGENDA ITEM #2 |
| | 770 & 808 Maple Ave –Gutter Installation & Transom Windows |
| | Jeremy Culver, Applicant |
| | Meeting Date: May 16, 2023 |
| | Received Application: March 28, 2023 |
| Impacts: | Ohio Historic Inventory |

Updated Information Since Motion to Table

Planning Department staff met on site with applicant on April 24, 2023. The applicant spoke to their gutter installer and they are able to install half round gutters per ADRB request.


Applicant agrees to restore the transom windows on 770 Maple Ave building. In order to meet building code efficiency requirements the applicant is proposing to remove the existing screen from in front of the transoms and install an additional single pane of glass. Planning Department staff spoke with Ken Rivera in the Building Department and Mr. Rivera confirmed that there are efficiency requirements but installing HVAC and insulation can also help meet these requirements.

Applicant would like to install the original transom grids on 808 Maple Ave with a black backing and no glass panes. The transoms on 808 Maple have been damaged or are missing due to a fire (see attached images). Site inspection on April 24, 2023 indicated that the transom windows on 808 Maple are in far more disrepair than the transoms on 770 Maple. The applicant can remove rear and interior transoms to replace missing transoms on the front façade along 808 Maple.

Staff Comment:

- It was not the intention of Planning Department staff to indicate that the transom windows on 808 Maple would need to be restored to match the transoms on 770 Maple.
- Planning Department staff feel that the building articulations lead to a logical separation in the front façade of the buildings. If there were different designs in the arches over the doorways, it would not detract from the overall style of the building.
- Planning Department staff feel that restoring the original grids on 808 Maple will improve the façade, as currently there is only one grid shown, the others are covered or are missing.
- The applicant proposes to leave the arches on 808 Maple as is until a tenant has been selected and the intended use is defined. The applicant will come

back to ADRB at a later date regarding transoms and doors on 808 Maple Ave.











Original Staff Report:

Introduction:

The Applicant, Jeremy Culver, has submitted a Certificate of Appropriateness Application for window installation/replacement, door replacement, covered parking, ADA ramp/patio, gutter installation, and front entry renovations proposed at 770 & 808 Maple Ave. The proposal involves renovating the Maple Ave Freight Depot into commercial space.

This property is Zoned Light Industrial (I-1) and is located on the State of Ohio Historical Inventory as the David J. Joseph Co. / Pittsburgh, Cincinnati, Chicago & St. Louis R.R., Pennsylvania, Panhandle Freight Depot.

Proposal

- Existing Windows- (770 & 808 Maple Ave)- not salvageable
 - o Material-wood
 - o Color-black
 - o Design- wood, one over one style
 - o Dimensions- varying
- Proposed Windows
 - o Material- wood, fibrex composite
 - o Color-black
 - Design- Andersen 100 series, single hung, arch top, fixed half slide; one over one style; opaque black top lite to match the existing arches on 808 Maple
 - o Dimensions- same as existing
- Existing Door- (808 Maple Ave east side)- not salvageable
 - Material- wood, plywood

- o Color-black
- Design- half light with possible transom
- o Dimensions- standard door opening
- Proposed Door
 - o Material-TBD
 - o Color- TBD
 - o Design- TBD
 - o Dimensions- same as existing
- Proposed Roof for Covered Parking-
 - Material- metal to match warehouse
 - o Color-silver
 - o Design- MasterRib Galvalume Manufacturer
 - Dimensions- located on west side of building; park 4 work trucks; approximately 52 feet x 21 feet x 13 feet to eave and 19 feet to peak.
- Existing Gutters- there are no existing gutters on the property
- Proposed Gutters
 - o Material- aluminum, Mastic Manufacturer
 - o Color-black
 - Design- 6" "K-style" gutter, with 4" round corrugated downspouts along south and north elevations.
- Proposed Entryway Doors
 - o Material- wood, aluminum clad
 - o Color-black
 - o Design- Pella Reserve Door, Andersen 100 series slider doors

- Dimensions- 48" wide to match other windows, which is a custom width. Andersen 100 sidelights.
- Proposed Entry Stoop-
 - Material- Split face CMU, brick, aluminum railing (AFCO Pro manufacturer), concrete
 - o Color- black railing, brick to match existing building
 - Design- Split face CMU foundation to mimic the existing limestone foundation of the building. Brick columns to match existing brick with limestone cap, Black railing infill. Brushed finish concrete steps and slab.
 - o Dimensions- Approximately 11 feet x 9 feet x 2 feet tall
- Proposed ADA Ramp/Patio-
 - Material- Split face CMU, brick, aluminum railing (AFCO Pro manufacturer), composite decking (Timbertech)
 - Color- black railing, pecan Timbertech decking, brick to match existing building.
 - Design- Split face CMU foundation to mimic the existing limestone foundation of the building. Brick columns to match existing brick with limestone cap. Black railing infill. Decking to be composite Timbertech with concealed fasteners.
 - o Dimensions- Approximately 36 feet x 24 feet x 2 feet tall

Administrative COA

On March 24, 2023 an Administrative COA was granted to remove the existing fence along Maple Ave and East Ave. Install a new 6-foot tall black aluminum picket fence with brick columns along Maple Ave and East Ave. The COA also included painting the existing wood trim on building like for like (dark gray/black) and paint metal addition to match.

ADRB Policies & Guidelines

This application broaches the topic of gutters, roofs, and windows in the ADRB Policies and Guidelines.

<u>Gutters</u>

Requests for Certificates of Appropriateness involving new construction/replacement of gutters will be treated by the Board as follows:

- A. Every effort should be made to repair/reconstruct existing box, trough, or other original gutters with original materials to retain the original construction and appearance.
- B. The following relining materials may be substituted for original metal linings if the existing metal is proven to be beyond repair:
 - 1. Rubberized rolled roofing material
 - 2. Polyester rolled ("rubber") roofing material
- C. Tar (aka "pitch", "coal tar", etc.) patching of original gutters will only be approved if such "repair" efforts had been undertaken on the property prior to 1/1/86, and is subsequently requested as a "temporary" repair until a permanent improvement is made.
- D. If the existing gutters are proven beyond saving and a bypass system is necessary, one of the following reconstruction methods may be approved.
 Bypass System Type II is the preferred method. All architectural details removed during bypass installation must be reinstalled or replaced.

<u>Roofs</u>

Asphalt Roofs

Dimensional roofing is preferred in all cases.

<u>Windows</u>

General Window Regulations & Guidelines

Critical Parts of Windows that Shall Not Be Altered

The following items will be considered a critical part of the exterior architectural/design elements that shall not be altered on a structure:

- 1. The specific location of each individual window.
- 2. The specific style of each individual window.

3. The number of panes (lights/grids/sashes) of each individual window. (example: 2x2 grid/pane, 4x4 grid/pane, 9x9 grid/pane)

4. The specific dimensions of each individual window.

5. The specific treatment of the framing for each individual window.

6. The size, width, and placement of window parts, such as but not limited to the sashes, muntins, rail, casing, stile, stool, and apron shall remain unchanged. If these parts are on the exterior of the window, they shall remain on the exterior of the window, (i.e. exterior muntins shall not be moved to the interior of the window pane).

7. The relationship of the above elements and/or related elements for each window in the overall window treatment/design of a structure.

Window Work approval by the Architectural Design Review Board

Replacement of Significantly Damaged or Missing Windows

In the event that the window is significantly damaged or missing, the Architectural Design Review Board may be able to approve a Certificate of Appropriateness for window replacement with a broader list of window types, as long as the proposed window meets the General Window Regulations & Guidelines. This is subject to the following clauses:

1. Window is significantly damaged: This means that the window is damaged or rotted 50% or more, or is missing key components.

- o Half of the window is missing
- o Missing window sash and/or frame
- o Damaged/Missing window sill
- o Photo evidence shall be required. A site visit may be requested.

2. Window is missing: the window is missing, leaving only a window opening in the façade or a bricked in place where the window once was.

o Photo evidence shall be required. A site visit may be requested.

3. If the window exists but is significantly damaged, the applicant shall provide written or verbal testimony from an experienced window repair contractor or consultant to attest to the window being more than 50% damaged. The ADRB may ask for examples of other projects that the window repair contractor or consultant has completed.

4. The ADRB shall make the determination of whether the windows meet the definition of "Significantly Damaged or Missing Windows."

<u>List of Approved Replacements for Significantly Damaged or Missing Windows</u>- To the extent the design of the original window is known, the window must meet the General Window Regulations & Guidelines

 Andersen 100 Series Fibrex (40% Wood Fiber, 60% Polymer) Exterior & Interior

Considerations for Window Replacements:

When the ADRB is reviewing a Certificate of Appropriateness for window replacement, the following information will be considered to determine the appropriateness of replacing historic windows:

- 1. That multiple avenues of preserving the historic windows have been pursued, including consulting a historic window preservation specialist or contractor with demonstrable background and experience in preserving historic windows.
- 2. Difficulty in repairing the existing wood windows or difficulty in obtaining a contractor to repair the existing wood windows.
- 3. Difficulty in obtaining new wood windows or wood composite windows that match the existing wood windows.
- 4. The structure or portion of structure is comparatively more modern or newer than other houses and principal structures in the immediate area. This can include new additions of a structure.
- 5. That the request for window replacement is part of a large scale renovation project in a building that is substantial disrepair and would be in danger of demolition if not for the renovation project.

ADRB requires that the applicants to provide written evidence to support these considerations, including estimates, quotes, and/or recommendations from a professional and/or letters on letterhead with signature of the professional(s) involved in the assessment.

Other Window Replacement Types

Commercial Windows and Industrial Windows

Windows for businesses, commercial structures, and heavy industrial structures shall be considered on a case-by-case basis. There are cases where commercial and industrial structures require a different window type than the existing window. When the proposal is not appropriate for staff administrative review, ADRB will consider all relevant factors, including:

A. Replacement windows can be any material appropriate to the structure, including metal products.

- B. The replacement window shall replicate the size and transparency of the existing window (if reducing or filling a window, or creating a new opening, please refer to that section of the window guidelines).
 - If the applicant is proposing a window that does not match the existing design, sufficient justification for the change must be provided to the ADRB. This may include but is not limited to considerations such as the viability of the business operation and/or historical examples of why the proposed change is appropriate.

Staff Comments:

- Applicant will attempt to save wood window frames where possible so the new windows can be installed in like kind with the original. A black wood frame will be installed between the window and brick, similar to original.
- Applicant proposes to cover the window arches (transom) over the doors to match the arches over the doors on the connecting building (808 Maple).
 - Applicant states the transoms are covered with screens and many panes are broken.
 - Planning Department staff recommends restoring/repairing the small window panes in the transoms over the doors.
- The only work being completed on 808 Maple, during this phase, is window and door replacement and gutter installation. Large wood doors on 808 Maple are not being replaced at this time.
 - Applicant is aware that they may need to return to ADRB for exterior renovations to this property.
- Mr. Spurlock was not able to locate a historical photo of the Panhandle Freight Depot. However, he did indicate that the depot was constructed in 1888 (Victorian Period). The building is an example of Romanesque Revival/ Victorian Romanesque style, though it does have the inverted "U" window hoods typical of the Italianate and Second Empire styles.
 - Romanesque Revivals usually have a 1 over 1 window style.
 - Italianates and Second Empires most commonly have 2 over 2 or 1 over 1 window style.

Motion:

The ADRB may approve, modify, or deny the COA request as presented to the Board. Planning Department staff has prepared the following motions for the Board's consideration:

• ADRB move to <u>approve</u> the COA request for gutter installation (770 & 808 Maple) and transom repair (770 Maple) as proposed after determining it

maintains compliance with Section 2600 of the Hamilton Zoning Ordinance and ADRB Policies & Guidelines.

 ADRB move to <u>deny</u> the COA request as proposed, as it is not compliant with Section 2600 of the Hamilton Zoning Ordinance and/or ADRB Policies & Guidelines.

Attachments:

- 1. Exhibit A Location Map
- 2. Exhibit B Certificate of Appropriateness Application
- 3. Exhibit C Site Plan & Photos
- 4. Exhibit D Rendering & Material Specs
- 5. Exhibit E Ohio Historic Inventory Sheet

Exhibit A – Location Map




Exhibit B – Certificate of Appropriateness Application



Planning Department 345 High Street, 3rd floor Hamilton, Ohio 45011

Architectural Design Review Board

Phone: 513-785-7350

Fax: 513-785-7359

Email: hamiltonhistoric@hamilton-oh.gov

APPLICATION FOR A CERTIFICATE OF APPROPRIATENESS

Exterior changes made to buildings, outbuildings, landscapes, or other exterior features located within one of the City of Hamilton's Historic Areas or properties individually listed by Ordinance shall not be permitted unless and until the Architectural Design Review Board issues a Certificate of Appropriateness for the action. The ADRB will review the plans, monitor the work and administer the Architectural Conservation/Historic District section (Section 2600) of the Hamilton City Zoning Ordinance.

A fee will be charged for any Certificate of Appropriateness application that is required to be heard before the ADRB, <u>unless the proposed change is returning to or restoring to previous or original historic materials that can</u> <u>be referenced in past Architectural Design Review Board or other official City of Hamilton/State of Ohio Historic</u> <u>Inventory records</u>. A proposal that is Like for Like (A repair or improvement in relation to a property in which the repair or improvement utilizes the existing materials/colors and replaces them with matching materials) does not require ADRB review and will be approved by the Secretary.

A nonrefundable fifty-dollar (\$50.00) fee for Residential property or one-hundred-dollar (\$100.00) fee for Commercial property is due when a Certificate of Appropriateness application is submitted.

| Fee Schedule | | |
|--|-------------|------------|
| Proposal: | Residential | Commercial |
| Exterior Change | \$50 | \$100 |
| Like for Like Work (no board review) | \$0 | \$0 |
| Return to Original Historic Materials | \$0 | \$0 |
| Work without COA Fee (First Occurrence) | \$100 | \$200 |
| Work W/O COA Fee (Multiple Occurrences) | \$300 | \$600 |

Property Address: 770 & 808 Maple Ave., Hamilton OH 45011

Applicant Name: Meyer Brothers and Sons (Jeremy Culver)

Applicant Mailing Address: 2275 Millville Ave., Hamilton OH 45011

Owner/s Name: Same as above

Rev. 01/01/2023

| | Structure/House (put N/A if no | t known): N/A |
|--|--|--|
| Paint | | ided (often required) |
| Appearance of (| Color: | |
| Color Name & M | | |
| Location (body, | window trim, specific trim, acce | ent: |
| Siding Existing Siding | Sample Provi (style, material, color, location) | |
| Proposed Siding | g (style, material, color, locatio | n): |
| Manufacturer: | | Proposed Size: |
| copy of Preser provide picture proposed. | vation Brief 8, concerning si es and document extensive r *Roofing r | ng, per ADRB Guidelines, applicant must be provided a iding. It is HIGHLY recommended that applicant reasons why vinyl or non-historic siding is being may require a building permit from the Building Department* |
| | | black composition roof and existing metal roof to remain |
| Proposed Roof | | sed parking structure roof to match existing metal Location: New Parking Structure on West side of building |
| NOTE: Per ADF material as the other non- hist | RB Guidelines, it is recomme original window opening. C oric windows, it is recomme | Type (if applicable): Single Hung Arch top; fixed, halfslide ended that proposed windows are the same size and overing of windows is highly discouraged. For vinyl or ended to document existing windows, including the |
| 2.3.0.2.1. | reasons why original windov *Chain-link is disco (type, material, color): | ws should be replaced. uraged unless certain conditions are met defined by ADRB* |
| Existing Fence | e (type, material, color, location | SALE MASS |
| Existing Fence | a state i successive a secol de secol | n, course): |
| Existing Fence Proposed Fence | | vised that all replaced gutters match the look of the existing |
| Existing Fence (Proposed Fence Gutters Existing Gutter (Proposed Gutter | *It is adv (material, style, location, color) r (material, style, location, colo | vised that all replaced gutters match the look of the existing |
| Existing Fence (Proposed Fence) Gutters Existing Gutter (Proposed Gutte Manufacturer: | *It is adv (material, style, location, color) r (material, style, location, color Mastic (Black gutters and | vised that all replaced gutters match the look of the existing : <u>None existing</u> or): <u>6""K-style" gutter, black w/4" round corrugated downspouts (SouthNorth Elevations)</u> downspouts to match trim) |
| Existing Fence (Proposed Fence) Existing Gutter (Proposed Gutter Manufacturer: | *It is adv (material, style, location, color) r (material, style, location, color Mastic (Black gutters and style, material, location, color): | vised that all replaced gutters match the look of the existing): <u>None existing</u> (): ^{6*} "K-style" gutter, black w/4" round corrugated downspouts (South North Elevations) |
| Existing Fence (Proposed Fence) Existing Gutter (Proposed Gutter Manufacturer: | *It is adv (material, style, location, color) r (material, style, location, color Mastic (Black gutters and style, material, location, color): | vised that all replaced gutters match the look of the existing): <u>None existing</u> or): <u>6" "K-style" guter, black w/4" round corrugated downspouts (SouthNorth Elevations)</u> downspouts to match trim) |

CHECK ALL THAT APPLY & FILL IN THE CORRESPONDING INFORMATION

DESCRIPTION OF WORK TO BE PERFORMED

Please <u>specify</u> the exact location on the structure, the nature of the work, the materials and methods to be used, and the existing historic features to be repaired or replaced not previously mentioned. Landscape, fence, and out buildings, etc., should include a sketch of the property showing the proposed location. In order to make an appropriate, fair and timely decision the ADRB may request additional detailed information. This may include plans, sketches, photographs, and information about the materials to be used, including brochures, catalog information, and paint chips. The more information provided, the better:

| See Attached document. |
|--|
| U |
| Demolition |
| NOTE: <u>2600 Certificate of Appropriateness – Demolition</u> : In the event an application for a Certificate of Appropriateness includes demolition of any property in the Architectural Conservation/Historic District the applicant shall be required to submit evidence to the Architectural Design Review Board indicating that two of the following conditions prevail: |
| A. That the property proposed for demolition is not inherently consistent with other properties in its area of the Architectural Conservation/Historic District. For example, it may have been built at a time outside of the period of significance of the historic district. |
| B. That the property proposed for demolition contains no features of architectural and/or historical significance. |
| C. That there is no reasonable economic use for the property as it exists or as it might be rehabilitated that there is no feasible means or prudent alternative to demolition, |
| D. Existing structures listed in Section 2603.1(Central Area Building Inventory) shall be maintained. No demolition proposal will be accepted: |
| Without evidence showing significant financial infeasibility of preserving, rehabilitating, restoring or reconstructing the structure. An example might be providing a pro forma that documents how the costs of rehabilitation could not be recuperated reasonably through the reuse of the building. |
| 2. Without a detailed plan of demolition and potential reuse of the property. |
| Without a detailed plan of preserving any remaining exterior architectural features and/or historical features of the structure and site. |
| E. The demolition of the property would contribute to a significant economic development purpose or proposal that furthers the City of Hamilton's comprehensive plan, Plan Hamilton. That the demolition would have a strategic economic impact to the historic district or neighborhood as a whole beyond the individual property. |
| Please attach supporting information as a separate document as necessary |
| Applications can be submitted electronically to HamiltonHistoric@hamilton-oh.gov |

ADRB Application:

Roof/Parking Structure -

- The existing roof is made up of composite shingles on the historic brick structure while the
 existing warehouse roof is a MasterRib Galvalume metal roof. These roofs will be maintained
- The new roof structure that is proposed to be an outdoor parking area is proposed to match the MasterRib Galvalume metal roof since it sits in line with this existing metal roof. We are open to the material on this roof being metal or composite if ADRB has a preference.

Windows and Doors -

- · Existing windows have deteriorated to point of being beyond repair
- The existing window and door openings will be maintained within the brick structure to preserve the original architecture.
- We will attempt to save the wood frames where possible so that the new windows will be installed in like kind with the original (all windows at all areas will be installed with a black wood frame between the brick and the window to be in keeping with the original build)
- Since we are changing the use from a freight depot to a showroom and office, more natural light
 and natural ventilation is required within the showroom and office of 707 Maple Ave.
- Existing large door openings on the 770 Maple Ave portion of the building (eastern most portion)
 will be changed to a collection of Andersen 100 series windows that fit stylistically with simplicity
 and consistency see drawings. We want to meet functional needs but keep the attention on the
 architecture of the building and not detract from it. On the South elevation of 707, we'll be infilling
 the arch portion of the large openings with black painted wood to match the existing arches which
 are currently infilled and will remain (see drawings). These infills will allow for exterior illumination
 by adding light fixtures above.
- The main entry door will be a 48" wide Pella Reserve (their top of the line collection) which is a
 wood door with a black aluminum cladding for durability and weather resistance on the exterior.
 We would like it to be 48" to maintain the proportion and vocabulary of the other window
 compositions on this elevation and there are few manufacturers that will allow for this width.
- The windows on the 2-story portion of 808 Maple Ave. (eastern most portion of the building) are single hung arch top windows. These are available in Andersen 100 series and will match the brick openings as they are.
- · All windows and doors will be black to match with the existing window, door, and trim color

Gutters/Downpouts -

- · There are no existing gutters on this structure
- We believe that traditional K-style gutters that are 6" will fit best from a style and architecture standpoint (as well as functionally)
- We believe that 4" corrugated round downspouts will fit best from a style and architecture standpoint
- Gutters and downspouts will be Mastic brand and will be black to match the existing trim, windows, and accents

Entry Stoop -

- For the new main entry of 707 Maple Ave, the materials to be used are the following to blend as best as possible with existing materials of the building -
 - Split face CMU for the "foundation" to mimic the existing limestone foundation of the building


- · Brick columns to match the existing brick; black railing infill that is AFCO brand
- Broom finish concrete for the steps and slab
- See drawings


ADA Ramp & Deck -

- For the ADA ramp and deck of 707 Maple Ave, the materials to be used are the following to blend as best as possible with existing materials of the building -
 - Split face CMU for the "foundation" to mimic the existing limestone foundation of the building
 - Brick columns to match the existing brick; black railing infill that is AFCO brand
 - Decking to be composite Timbertech "Pecan" with concealed fasteners
 - See drawings

Exhibit C - Site Plan & Photos






































Exhibit D – Rendering & Material Specs





WHY YOU CAN TRUST PELLA

At Pella, we don't just create windows and doors. We innovate with purpose, design with passion, build with integrity and deliver with pride.

RATED #1 BY HOMEOWNERS FOR INNOVATION' We are continually striving to improve what we do and how we do it. That drive has earned us 150 patents and counting for amazing innovations. In 1625 we opened our doors with the patented Rolsceree' restatible screen, a time-tested innovation that is still one of our most desired features today.

RATED #1 BY HOMEOWNERS FOR HIGHEST QUALITY

We make products specifically for you with meticulous care and attention. Our wood craftmen have been honing their akills, on average, for over 14 years - their Jonger than it takes for mast to earn their JhD. And to dean't step there. Our product designs are tested beyond industry tandards, so you can trust them to perform. Door designs are tested to 1000 open and close cylose, and double-hung and casement window designs are tested at least 8,000 times.

THE BEST LIMITED LIFETIME WARRANTY FOR WOOD WINDOWS AND PATIO DOORS' You can feel confident in your investment. We pride subsets on providing exceptional quality, exceeding expectations and going beyond requirements. That's why we stand behind all of our wood windows and patio doors with a limited lifetime worranty.²

Study of homesener perceptions of leading national brands. Study commensioner by man, nam.
 Hand on strong-lang writes introleut ensemble of leading anisonal model quick work and model gains (since hand). Ease writes i trobad warranties for strong land details, including exceptions and instantions, at pells combeneng, or context field. Comment Sandon.



WHY CHOOSE WOOD?

Get the beauty and warmth of natural wood, our most customizable designs and exceptional energy efficiency. All Pella wood products are made with high-quality wood, metal and manufacturing processes, regardless of product line.

EXCLUSIVE WOOD PROTECTION Pells's exclusive EnduraGuard⁹ wood protection is applied after the pieces have been sut and milled, but prior to final assembly, providing advanced protection against the elements.

DESIGNED FOR LONG-LASTING DURABILITY Intentional Jambon till design helps seal the end grain of the wood end elevates is off the rough opening, reducing the potential to absorb moliture. For added strengt end durability, our three-way corner joint are made up of mortiseand-tenon, metal fatterers and commercial adhesive.

QUALITY EXTERIOR AND INTERIOR FINISHES Extruded aluminum-slad exteriors feature through-stills construction for exceptional durability and EnduraClad[®] finishes that resist fading and chalking, Interiors can be factory pre-finishes to accer time. Our profinish is applied prior to final essembly and kiln-cured for a quality esthetic.



THE BEST LIMITED LIFETIME WARRANTY FOR WOOD WINDOWS AND PATIO DOORS" You can be consider in your (investment, Ar Nells, we are committed to designing and building weed products with exceptional quelity and durability. This is supported by WCO MODIFICIENT CONSTRUCTION OF A support of the investment of the support of the support of the investment of the support of

Page 30







AVAILABLE IN THESE WINDOW AND PATIO DOOR STYLES:

EVERY DETAIL MATTERS

41HDOW + 0000

PERO WINNE

Winner of the 2019 Most Innovative Window from Window and Door Mension

20

19

INTEGRAL LIGHT TECHNOLOGY* Pells's Integral Light Technology helps capture the look of true-divided-light without ascrificing energy efficiency.

AUTHENTIC HARDWARE Complement your project with historially subtentic spoon-lock window hardware, Our Antiek casement window hardware is happing by partod funtions to deliver subtentic, traditional tayle. Add chem to patio doors with prenium hardware created in collaboration with Baldwint.

INTEGRAL LIGHT TECHNOLOGY*

THROUGH-STILE CONSTRUCTION Essential to the tradition of window making, but joinery and through-still econstruction create eithentic proportions and emulise historic window design.

Further your aesthetics with the putty profile, recreated with historically accurate angles – roviding meaningful depth and a realistic shadow. Palla Reserve products offer the industry's deepest tash dimensions for a richer and more dramatic aesthetic for your project.

HISTORIC PUTTY PROFILE

Revel in the authenticity and bring your design vision to life. Exadding the tenets of traditional designs. Pella Reserve – Traditional products provide historical elements with uncompromised attention to detail.

WHY CHOOSE PELLA* RESERVE[™] – TRADITIONAL?











Exhibit E – Ohio Historic Inventory Sheet

| OHIO HISTORIC | INVENTORY | Ohio Historic Preservation Office Ohio Historical Center Columbus, Ohio 43211 | | | |
|--|--|--|--|--|--|
| 1. No. BUT - 221-9 2. County | 4. Present Name(s) David J. Joseph Co. | sent Name(s) David J. Joseph Co. Source Name(s) Sourch, Cincinnati, Chicago & St. Louis R.R., Pennsylvania, | | | |
| Butler 3. Location of Negatives Hamilton Planning Dept. | 5. Other Name(s) Pittsbuch, Cincinnati, Chicago & St. L Panhandle Freight Depot | | | | |
| 8. Specific Location | 16. Thematic Category | 28. No. of Stories 2/1 | | | |
| West of Ninth St., north of | Maple transportation | 29. Basement? Yes D No 35 | | | |
| St. along railroad tracks. | c1890 | 30. Foundation Material | | | |
| City or Town If Rural, Township & Hamilton | Vicinity 18. Style or Design | Stone 31. Walr Construction | | | |
| Site Plan with North Arrow | N 19. Architect or Engineer | Brick load=bearing 32. Roof Type & Material | | | |
| HIGH | 20. Contractor or Builder | Gable/tar paper 33. No. of Bays | | | |
| The second second | 21. Original Use, if apparent freight depot | Front 2 Side 3 | | | |
| | 22. Present Use | DFICK | | | |
| MAPLE | storage? 23. Ownership Public D | 35. Plan Shape rectangle 36. Changes Addition 🗆 b | | | |
| Coordinates | 24. Owner's Name & Address. | 36. Changes Addition □ (Explain Altered S in #42) Moved □ | | | |
| Lat. Long. U.T.M. Reference | if known | 37. Condition Interior | | | |
| 671072043/3 | 360 | Exterior_fair | | | |
| one Easting Northin | D. blief | 38. Preservation Yes 🗆 | | | |
| Building X O | bject 25. Local Contact Person or Organization | Underway? No 53 39. Endangered? Yes 🗆 | | | |
| I. On National Yes ☐ 12. Is It Register? No S Eligible? | Yes D Hamilton Planning Dept. No 8 27. Other Surveys in Which Included | By What? No 🕱 | | | |
| Hist. Dist.? No S Potent'l? | Yes I No X | 40. Visible from Yes ≫ Public Road? No □ | | | |
| 5. Name of Established District | | 41. Distance from and Frontage on Road 15' PEOM MAPLE | | | |
| is two bays by three bays The distinctive roofline o eaves supported by extende with stone segmental arch windows of the lower section several have been blocked 3. History and Significance This building was used as t St. Louis R.R., which was 1 | wes f two portions: a two story section whic wide and a one story rectangular section f this building features wide, overhangi d rafter tails. Both sections have wind lintels decorated with a keystone. The on are in varying states of integrity, a up. A brick corbelling treatment decora (ov he freight depot for the Pittsburgh, Cin ater known as the Pennsylvania or Panhan ng is important for its associations wit | ind ows s tes er) icinnati, Chicago and idle Railroad. Despite | | | |
| is a wide expanse of railro | d residential, commercial and industrial | | | | |
| 5. Sources of Information | | 46. Prepared by Rita Walsh 47. Organization Mismi Purchase Ass'n | | | |
| | An Imperial Atlas and Art Folio, | Rita Walsh | | | |

42. the building.

Continuation Sheet: Specify Section & Item (use additional Continuation Sheets if necessary)

The Ohio Historic Preservation Office files contain additional information for this property. Information may include: newspaper clippings, church bulletins, maps or additional text.



| То: | Architectural Design Review Board |
|----------|--------------------------------------|
| From: | Dani Baxter |
| Subject: | New Business - AGENDA ITEM #1 |
| | 417 N 2nd St– Window Replacement |
| | Joe Kunkel, Applicant |
| | Meeting Date: May 16, 2023 |
| | Received Application: April 27, 2023 |
| Impacts: | German Village Historic District |

Introduction:

The Applicant, Joe Kunkel, has submitted a Certificate of Appropriateness Application for window replacement proposed at 417 N 2nd Street. The proposal involves replacing the side and rear basement windows with glass block and replacing the front façade basement windows with custom built wood frame windows.

This property is located within the German Village Historic District and is Zoned Business Planned Development. This property is located on the State of Ohio Historical Inventory and is listed as the William Hurin House (BUT059109).

Proposal

- Existing Windows- assumed to be original
 - o Material-wood
 - o Design- only frames remaining, boarded up
 - o Dimensions- varying, replacing all basement windows
- Proposed
 - o Material- glass block and custom built wood frame
 - Design- opaque glass block (sides and rear); wood frame and double pane fixed glass, close to like for like (front)
 - o Dimensions- same as existing

Administrative Approvals:

• On April 4, 2023 an Administrative COA was issued for like-for-like repair and replacement of front porch. Repair and replace damaged wood siding with like material, as needed.

Hamilton Zoning Ordinance

ADRB Policies & Guidelines

This application broaches the topic of windows in the ADRB Policies and Guidelines.

General Window Regulations & Guidelines

A. Critical Parts of Windows that Shall Not Be Altered

The following items will be considered a critical part of the exterior architectural/design elements that shall not be altered on a structure:

- 1. The specific location of each individual window.
- 2. The specific style of each individual window.

3. The number of panes (lights/grids/sashes) of each individual window. (example: 2x2 grid/pane, 4x4 grid/pane, 9x9 grid/pane)

4. The specific dimensions of each individual window.

5. The specific treatment of the framing for each individual window.

6. The size, width, and placement of window parts, such as but not limited to the sashes, muntins, rail, casing, stile, stool, and apron shall remain unchanged. If these parts are on the exterior of the window, they shall remain on the exterior of the window, (i.e. exterior muntins shall not be moved to the interior of the window pane).

7. The relationship of the above elements and/or related elements for each window in the overall window treatment/design of a structure.

Window Work approval by the Architectural Design Review Board

Replacement of Significantly Damaged or Missing Windows

In the event that the window is significantly damaged or missing, the Architectural Design Review Board may be able to approve a Certificate of Appropriateness for window replacement with a broader list of window types, as long as the proposed window meets the General Window Regulations & Guidelines. This is subject to the following clauses:

1. Window is significantly damaged: This means that the window is damaged or rotted 50% or more, or is missing key components.

o Half of the window is missing

- o Missing window sash and/or frame
- o Damaged/Missing window sill
- o Photo evidence shall be required. A site visit may be requested.

2. Window is missing: the window is missing, leaving only a window opening in the façade or a bricked in place where the window once was.

o Photo evidence shall be required. A site visit may be requested.

3. If the window exists but is significantly damaged, the applicant shall provide written or verbal testimony from an experienced window repair contractor or consultant to attest to the window being more than 50% damaged. The ADRB may ask for examples of other projects that the window repair contractor or consultant has completed.

4. The ADRB shall make the determination of whether the windows meet the definition of "Significantly Damaged or Missing Windows."

Additional Window Guidance

A. In the event that some windows on a structure can be repaired and others have been determined by the Architectural Design Review Board to meet the criteria for "Significantly Damaged or Missing Windows," the ADRB may ask that, where possible, historic windows be moved to primary facades and the new windows be installed on side and rear facades.

B. Considerations for Window Replacements:

When the ADRB is reviewing a Certificate of Appropriateness for window replacement, the following information will be considered to determine the appropriateness of replacing historic windows:

1. That multiple avenues of preserving the historic windows have been pursued, including consulting a historic window preservation specialist or contractor with demonstrable background and experience in preserving historic windows.

2. Difficulty in repairing the existing wood windows or difficulty in obtaining a contractor to repair the existing wood windows.

3. Difficulty in obtaining new wood windows or wood composite windows that match the existing wood windows.

4. The structure or portion of structure is comparatively more modern or newer than other houses and principal structures in the immediate area. This can include new additions of a structure.

5. That the request for window replacement is part of a large scale renovation project in a building that is substantial disrepair and would be in danger of demolition if not for the renovation project.

ADRB requires that the applicants to provide written evidence to support these considerations, including estimates, quotes, and/or recommendations from a professional and/or letters on letterhead with signature of the professional(s) involved in the assessment.

C. Other Window Replacement Types

1. Glass Block Windows

Glass Block windows can be considered where the existing basement windows are damaged, deteriorated, or missing or where the existing basement windows pose a safety concern (history of break-ins, etc.)

Glass Block may be considered in an accessory structure when windows are damaged, deteriorated, or missing or the windows pose a safety concern (history of break-ins, etc.) where the window is not visible from the street or sidewalk.

Glass block has been around since the 1880s and can be appropriate for industrial, commercial, mixed use, and residential properties within the context outlined in the guidelines. Historical use of glass block on the property or on properties of the same era and type can be considered when making a decision.

Staff Comments:

- 1. Applicant states that basement windows have water damage beyond repair on all sill plates, there is no glass left in the grids, existing fasteners are rusted, and windows provide no security or insulation. Front façade windows will be a similar like for like replacement.
- Applicant is proposing to use Jack Williams Glass Block to install side basement windows. This contractor also installed the glass block at 401 N 2nd, 309 N 2nd, and 407 N 3rd St.

Motion:

The ADRB may approve, modify, or deny the COA request as presented to the Board. Planning Department staff has prepared the following motions for the Board's consideration:

- ADRB move to <u>approve</u> the COA request to replace the side and rear basement windows with glass block and the front façade basement windows with custom built wood frame windows as proposed after determining it maintains compliance with Section 2600 of the Hamilton Zoning Ordinance and ADRB Policies & Guidelines.
- ADRB move to <u>deny</u> the COA request as proposed, as it is not compliant with Section 2600 of the Hamilton Zoning Ordinance and/or ADRB Policies & Guidelines.

Attachments:

- 1. Exhibit A Location Map
- 2. Exhibit B Certificate of Appropriateness Application
- 3. Exhibit C Site Photos
- 4. Exhibit D Glass Block Example
- 5. Exhibit E Ohio Historic Inventory document

Exhibit A – Location Map



Exhibit B – Certificate of Appropriateness Application



Planning Department

Phone: 513-785-7350

Architectural Design Review Board Fax: 513-785-7359 Email: hamiltonhistoric@hamilton-oh.gov

APPLICATION FOR A CERTIFICATE OF APPROPRIATENESS

Exterior changes made to buildings, outbuildings, landscapes, or other exterior features located within one of the City of Hamilton's Historic Areas or properties individually listed by Ordinance shall not be permitted unless and until the Architectural Design Review Board issues a Certificate of Appropriateness for the action. The ADRB will review the plans, monitor the work and administer the Architectural Conservation/Historic District section (Section 2600) of the Hamilton City Zoning Ordinance.

A fee will be charged for any Certificate of Appropriateness application that is required to be heard before the ADRB, <u>unless the proposed change is returning to or restoring to previous or original historic materials that can be referenced in past Architectural Design Review Board or other official City of Hamilton/State of Ohio Historic Inventory records. A proposal that is Like for Like (A repair or Improvement in relation to a property in which the repair or improvement utilizes the existing materials/colors and replaces them with matching materials) does not require ADRB review and will be approved by the Secretary.</u>

A nonrefundable fifty-dollar (\$50.00) fee for Residential property or one-hundred-dollar (\$100.00) fee for Commercial property is due when a Certificate of Appropriateness application is submitted.

| Fee Schedule | | |
|--|-------------|------------|
| Proposal: | Residential | Commercial |
| Exterior Change | \$50 | \$100 |
| Like for Like Work (no board review) | \$0 | \$0 |
| Return to Original Historic Materials | \$0 | \$0 |
| Work without COA Fee (First Occurrence) | \$100 | \$200 |
| Work W/O COA Fee (Multiple Occurrences) | \$300 | \$600 |

Property Address: 417 N. Second st.

Applicant Name: Joe Kunkel

Applicant Mailing Address: 905 Millville ave

Owner/s Name: Sheryl Sibler

Applicant Signatures

Owner Mailing Address: 5189 Cincinnati dayton rd. Lib twp. 45044

Daytime Contact Phone: 5132003031

____ beambridgeco@gmail.com

Date: 4-25-20

APPLICANTS ARE HIGHLY ENCOURAGED TO APPEAR BEFORE THE BOARD TO SUPPORT THEIR APPLICATION.

Please see Page 4 for the Meeting Dates and Application Deadlines.

Rev. 01/01/2023

CHECK ALL THAT APPLY & FILL IN THE CORRESPONDING INFORMATION

| Paint | Sample Provided (often required) | | | | |
|--|---|--|--|--|--|
| Appearance of C | olor: | | | | |
| | nufacturer | | | | |
| and the second | indow trim, specific trim, accent: | | | | |
| Siding Existing Siding (s | Sample Provided tyle, material, color, location): | | | | |
| Proposed Siding | (style, material, color, location): | | | | |
| Manufacturer: | Proposed Size: | | | | |
| copy of Preserv | ing vinyl or aluminum siding, per ADRB Guidelines, applicant must be provided ation Brief 8, concerning siding. It is HIGHLY recommended that applicant and document extensive reasons why vinyl or non-historic siding is being | | | | |
| Roof Existing Roof (m | *Roofing may require a building permit from the Building Department terial, style, color): | | | | |
| Proposed Roof (| naterial, style, color): | | | | |
| | Location: | | | | |
| Windows / Door Existing Window | /Door (style, meterial, size, color, location): Beasement. Wood | | | | |
| Proposed Windo | vs/Door (style, material, size, color, location): Glassblock on all sides exept for streetside. | | | | |
| | Type (If applicable); | | | | |
| material as the other non- histe | B Guidelines, it is recommended that proposed windows are the same size and original window opening. Covering of windows is highly discouraged. For vinyl or ric windows, it is recommended to document existing windows, including the asons why original windows should be replaced. | | | | |
| Fence Existing Fence (| *Chain-link is discouraged unless certain conditions are met defined by ADR /pe, material, color): | | | | |
| Proposed Fence | (type, material, color, location, course): | | | | |
| Gutters Existing Gutter (| "It is advised that all replaced gutters match the look of the existin naterial, style, location, color): | | | | |
| Proposed Gutter | (material, style, location, color): | | | | |
| Manufacturer: | | | | | |
| Soffit | yle, material, location, color): | | | | |
| and the second sec | style, material, location, color): | | | | |
| Proposed Soffit | | | | | |
| Proposed Soffit | | | | | |

CHECK ALL THAT APPLY & FILL IN THE CORRESPONDING INFORMATION

DESCRIPTION OF WORK TO BE PERFORMED

Please <u>specify</u> the exact location on the structure, the nature of the work, the materials and methods to be used, and the existing historic features to be repaired or replaced not previously mentioned. Landscape, fence, and out buildings, etc., should include a sketch of the property showing the proposed location, in order to make an appropriate, fair and timely decision the ADRB may request additional detailed information. This may include plans, sketches, photographs, and information about the materials to be used, including brochures, catalog information, and paint chips. The more information provided, the better:

Proposing glass block as replacement for existing basement windows due to water damge beyond repair on all sill plates. All exsisting fasteners are rusted through and current windows provide near zero security and no insulating value. Nor do any have glass left in them.

Like for like design on street facing window. All others to be glass block matching other houses in the village.

Demolition

NOTE: 2600 Certificate of Appropriateness – Demolition: In the event an application for a Certificate of Appropriateness includes demolition of any property in the Architectural Conservation/Historic District the applicant shall be required to submit evidence to the Architectural Design Review Board indicating that two of the following conditions prevail:

- A. That the property proposed for demolition is not inherently consistent with other properties in its area of the Architectural Conservation/Historic District. For example, it may have been built at a time putside of the period of significance of the historic district.
- B. That the property proposed for demolition contains no features of architectural and/or historical significance.
- C. That there is no reasonable according use for the property as it exists or as it might be rehabilitated, that there is no feasible means or prudent alternative to demolition,
- D. Existing structures listed in Section 2603,1(Central Area Building Inventory) shall be maintained. No demolition proposal will be accepted:

 Without evidence showing significant financial infeasibility of preserving, rehabilitating, restoring or reconstructing the structure. An example might be providing a pro-forma that documents how the costs of rehabilitation could not be recuperated reasonably through the reuse of the building.

2. Without a detailed plan of demolition and potential reuse of the property.

Without a detailed plan of preserving any remaining exterior architectural features and/or historical features of the structure and site.

E. The demolition of the property would contribute to a significant economic development purpose or proposal that furthers the City of Hamilton's comprehensive plan, Plan Hamilton. That the demolition would have a strategic economic impact to the historic district or neighborhood as a whole beyond the individual property.

Please attach supporting information as a separate document as necessary

Applications can be submitted electronically to HamiltonHistoric@hamilton-oh.gov

Exhibit C – Site Photos



Front Façade Windows



Right Façade Windows



Rear Façade Windows



Left Façade Windows



Exhibit D – Glass Block Example from 309 N 2nd St





Ohio Historical Center HISTORIC INVEN HIC Columbus, Ohio 43211 4. Present Name(s) I. No 591-9 No. 5 County 5. Other Name(s) Butler 3. Location of Negatives Hamilton Planning Dept. William Hurin House 16. Thematic Category 28. No. of Stories 6. Specific Location N 2 1/2 Commercial 29. Basement? Yes ⊠ No □ County 417 North Second Street 17. Date(s) or Period c1885 30. Foundation Material Rock Ashlar 7. City or Town If Rural, Township & Vicinity 18. Style or Design Butler 31. Wall Construction Queen Anne Hamilton 8. Site Plan with North Arrow 19. Architect or Engineer Frame 32. Roof Type & Material 20. Contractor or Builder Hip/asphalt shingle 33. No. of Bays Front 5 N Þ Side 4 Secon 21. Original Use, if apparent h Present Residence 34. Wall Treatment Clapboard/shingle 22. Present Use Apartments 35. Plan Shape Irregular Nam 23. Ownership Public D Private 25 Addition 36. Changes Altered D 윤 (Explain Altered 9. Coordinates in #42) 24. Owner's Name & Address, if known Lat. Long 37. Condition U.T.M. Reference 14 Interior 710188 16 4364020 Exterior fair Northing 25. Open to Public? Zone Easting Yes □ No ⊠ 38. Preservation Yes D Structure D Object D 0. Site Underway? Building X Endangered? 26. Local Contact Person or Organization 39. Yes □ No B By What? Yes ₪ No □ 11. On National Yes 🗆 12. Is It Eligible? Hamilton Planning Dept. No B Register? 27. Other Surveys in Which Included 14. District Potent'l? Yes B No D 13. Part of Estab. Yes 40. Visible from Public Road? Yes S No 🗆 Hist. Dist.? No E 15. Name of Established District 41. Distance from and Frontage on Road 42. Further Description of Important Features U Hip roof contains two gable projections, (one front, and side) and Other gable dormer in front. Some stick style detailing can be seen in the series of horizontial bands which encircle the building. The Name(s) 1 am slight second story overhang is decorated with imbricated shingles, as are the gable peaks. Front porch has arcade motif between the Hur porch posts. A small balcony is located atop this porch. 1 43. History and Significance Ho This house is significant as an example of Queen Anne architecture. In 1900 it was owned by William Hurin, a shoe merchant. 44. Description of Environment and Outbuildings This building is located in a residential neighborhood of similar scale, age, and style structures. 45. Sources of Information P.O. 46. Prepared by E. Tuttle U.S. Census, 1900 47. Organization Miami Purchase Ass'n. 48. Date 49. Revision Date(s) 2 - 84

Exhibit E – Ohio Historic Inventory document

| 51. Condition of Property Excellent Ruin Good/Fair Destroyed/Burned Deteriorated Date | 54. Farmstead | I Plan | | Ē |
|--|---------------|--------|---|---|
| 52. Historic Outbuildings and Dependencies | | | | |
| Barn Type(s) | | | | |
| | - | | - | |
| Corn Crib or Shed Smoke House Privy Summer Kitchen Spring House Garage Silo Ice House | | | | |
| Designed landscape features | | | | |
| Archaeological Feature: Observed Expected on Basis of Archival Research | | | | |
| Well Privy Cistern Foundation | | | | |
| Structural Rubble Formal Trash Dump Other | Ŀ | | | ÷ |

42. (Cont'd)

43. (Cont'd)